



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 187K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT BONNET INNER TRIM (NPA)	NOT NECESSARY	-	-
1	FRONT BONNET LOCK (NPA)	NOT NECESSARY	-	-
2	FRONT HEADLAMP L+R @\$1700.00	CRACKED	3,400.00	3,400.00
2	FRONT HEADLAMP BRACKET L+R (NPA)	NOT NECESSARY	-	-
1	FRONT GRILLE	CRACKED	597.00	597.00
1	FRONT GRILLE CHROME	CRACKED	275.50	275.50
1	FRONT GRILLE LOGO	NECESSARY	86.70	86.70
1	FRONT BUMPER	DEFORMED	2,347.00	2,347.00
2	FRONT BUMPER LOWER CHROME L+R (NPA)	NOT NECESSARY	-	-
2	FRONT BUMPER FOG LAMP GARNISH L+R (NPA)	NOT NECESSARY	-	-
2	FRONT BUMPER FOG LAMP L+R @\$228.00	CRACKED	456.00	456.00
2	FRONT BUMPER RETAINER L+R @\$136.00	NECESSARY	272.00	272.00
2	FRONT BUMPER BRACKET L+R (NPA)	NOT NECESSARY	-	-
2	FRONT BUMPER HEADLAMP NOZZLE L+R (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER REINFORCEMENT BAR (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER SPONGE (NPA)	NOT NECESSARY	-	-
1	SET FRONT BUMPER SENSOR (NPA)	NOT NECESSARY	-	-
2	FRONT FENDER L+R (NPA)	NOT NECESSARY	-	-
2	FRONT FENDER COWLING L+R (NPA)	NOT NECESSARY	-	-
1	FRONT SUPPORT PANEL (NPA)	NOT NECESSARY	-	-
1	FRONT SUPPORT PANEL TOP GARNISH	DEFORMED	316.00	316.00
2	FRONT HORN (NPA)	NOT NECESSARY	-	-
1	FRONT BRACE PANEL (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-775.02	-775.02
			6,975.18	6,975.18
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BONNET INNER TRIM CLIPS (SN)	NOT NECESSARY	120.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	120.00	30.00
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	120.00	10.00

Report Ref No. CS/SMO21003615/T1Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	120.00	-
			480.00	40.00
	LABOUR			
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT BONNET.		1,000.00	300.00
	SPRAY PAINT ON AFFECTED AREAS.		1,000.00	400.00
	TO CHECK WIRING AND HEADLAMP FOCUS.		60.00	30.00
	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS.		250.00	30.00
	TO RNR FRONT RADIATOR.	NOT NECESSARY	250.00	-
	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS.		400.00	100.00
	TO RNR HORN AND TEST FUNCTION.	NOT NECESSARY	120.00	-
			3,080.00	860.00
GRAND TOTAL			10,535.18	7,875.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,300.00

Report Ref No. CS/SMO21003615/T1Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.