

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS3/SMO21000061/GUqde2- 1	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Date:	21/04/2021	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 1152C	Veh. Inspected	GBJ 5925Y	
	Policy No.	D20MTPCVE001854	Coverage (\$)	0.00	
	Claim No.	CMTD2003605/MYE	Excess (\$)	0.00	
	Assign From	MELVIN YE YONG KANG	Assign Date	19/03/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	JTFHT02P300249128	Colour	SILVER	
	Odometer	68542 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	08/12/2020	Inspection Date	05/01/2021	
	Survey held at	CARSMITH PTE LTD			
		BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	<u>.</u>				