

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21003617/BTD3E2**Date:** 10/05/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW0010379200
Claimant Vehicle No :	SLK2183S	Insured Vehicle No :	GBA5469U
Date of Loss:	11/02/2021	Nature of Claim:	TP
		Claim No:	SNM21D200883/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2183S	Engine No:	L15B4407665
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11207666
Reg. Date:	10/01/2017 (Man. Year: 2016)	Odometer:	65068 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,998.80	2,705.52	17,293.28	86.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,660.00	2,290.00	4,370.00	65.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,658.80	4,995.52	21,663.28	81.26
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	26,658.80	4,000.00	22,658.80	85.00
+ GST 7.00/7.00% (S\$)	1,866.12	280.00	1,586.12	85.00
Nett Amount (S\$)	28,524.92	4,280.00	24,244.92	85.00

INSPECTION

Date of Assignment:	22/03/2021	
Date Inspected:	22/03/2021	Inspected At: Team Autopro Pte Ltd (Sin Ming) 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722
Estimated Period of Repair:	8.0 days	

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK2183S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	785.00 FL	*- FL
2	1		*FRONT FENDER INNER COWLING LH	Not Damaged	192.00 FL	*- FL
3	1		*FRONT FENDER ARCH GARNISH LH	Not Damaged	215.00 FL	*- FL
4	1		*HEADLAMP LH	Not Damaged	1,988.00 FL	*- FL
5	1		*HEADLAMP LOWER BRACKET LH	Not Damaged	189.00 FL	*- FL
6	1		*FRONT BUMPER	Not Damaged	988.70 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Not Damaged	117.00 FL	*- FL
8	1		*FRONT DOOR LH	Repair	1,280.00 FL	*- FL
9	1		*FRONT DOOR BLACK TAPE LH	Not Damaged	92.60 FL	*- FL
10	1		*FRONT DOOR WEATHERSTRIP LH	Not Damaged	194.40 FL	*- FL
11	1		*FRONT DOOR INNER LOCK LH	Not Damaged	523.00 FL	*- FL
12	1		*FRONT DOOR LOCK STRIKER LH	Not Damaged	68.00 FL	*- FL
13	1		*FRONT DOOR TRIMBOARD LH	Not Damaged	683.90 FL	*- FL
14	1		*FRONT DOOR FRAME RUBBER LH	Not Damaged	106.90 FL	*- FL
15	1		*FRONT DOOR OUTER CHROME HANDLE LH	Not Damaged	425.80 FL	*- FL
16	1		*DOOR CENTRE PILLAR LH	Not Damaged	678.00 FL	*- FL
17	1		*REAR DOOR LH	Dented	1,280.00 FL	*951.00 FL
18	1		*REAR DOOR BLACK TAPE LH	Necessary	106.00 FL	*88.50 FL
19	1		*REAR DOOR WEATHERSTRIP LH	Not Damaged	142.10 FL	*- FL
20	1		*REAR DOOR INNER LOCK LH	Not Damaged	328.90 FL	*- FL
21	1		*REAR DOOR LOCK STRIKER LH	Not Damaged	86.50 FL	*- FL
22	1		*REAR DOOR HINGE LH	Upper Bent	164.00 FL	*82.00 FL
23	1		*REAR DOOR CHECKER ARM LH	Not Damaged	102.80 FL	*- FL
24	1		*REAR DOOR TRIMBOARD LH	Not Damaged	683.90 FL	*- FL
25	1		*REAR DOOR FRAME RUBBER LH	Not Damaged	106.90 FL	*- FL
26	1		*REAR DOOR REGULATOR LH	Not Damaged	451.00 FL	*- FL
27	1		*REAR DOOR REGULATOR MOTOR LH	Not Damaged	385.60 FL	*- FL
28	1		*REAR DOOR GLASS CHANNEL LH	Not Damaged	445.70 FL	*- FL
29	1		*REAR DOOR OUTER CHROME HANDLE LH	Not Damaged	425.80 FL	*- FL
30	1		*SIDE SKIRT LH	Not Damaged	785.30 FL	*- FL
31	1		*SIDE MIRROR ASSY LH	Cut	887.00 FL	*495.20 FL
32	1		*REAR FENDER LH	Dented	1,452.80 FL	*891.20 FL
33	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	723.00 FL	*- FL
34	1		*REAR FENDER ARCH GARNISH LH	Not Damaged	218.30 FL	*- FL
35	1		*REAR BUMPER	Not Damaged	980.00 FL	*- FL
36	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	79.20 FL	*- FL
37	1		*REAR BUMPER SIDE GARNISH LH	Not Necessary	238.90 FL	*- FL
38	1		*TAILLAMP LH	Broken	658.30 FL	*460.50 FL
39	1		*REAR SHOCK ABSORBER LH	Not Damaged	653.20 FL	*- FL
40	1		*REAR AXLE	Not Damaged	890.00 FL	*- FL
41	1		*REAR WHEEL HUB WITH BEARING LH	Jammed	483.50 FL	*263.50 FL
42	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
43	1		*FRONT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
44	1		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*FRONT FENDER ARCH GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT DOOR SPEAKER	Not Necessary	210.00 FS	*- FS
48	1		*FRONT DOOR TRIMBOARD CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*DOOR CENTRE PILLAR SEALANT	Not Necessary	100.00 FS	*- FS
50	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*40.00 FS
51	1		*REAR DOOR SPEAKER	Not Damaged	210.00 FS	*- FS
52	1		*REAR DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
53	1		*SIDE SKIRT CLIPS	Not Necessary	50.00 FS	*- FS
54	1		*REAR FENDER SEALANT	Not Necessary	50.00 FS	*- FS
55	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
56	1		*REAR FENDER ARCH GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
57	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
58	1		*REAR BUMPER SIDE GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*TAILLAMP CLIPS	Necessary	50.00 FS	*20.00 FS
60	1		*TAILLAMP SEAL	Not Necessary	60.00 FS	*- FS
61	1		*REAR ALLOY RIM LH	Not Damaged	980.00 FS	*- FS
62	1		*REAR TYRE LH	Not Damaged	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	24,256.00	3,351.90
- List Item Discount on L Items 20.00/20.00% (S\$)	4,257.20	646.38
Total Parts (S\$)	19,998.80	2,705.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT DOOR COMPONENT	New	150.00	0.00
2	R&R FRONT SEAT	New	150.00	0.00
3	R&R DOOR CENTRE PILLAR INNER GARNISH	New	150.00	0.00
4	R&R FRONT SEATBELT	New	150.00	0.00
5	R&R REAR DOOR COMPONENT	New	150.00	80.00
6	R&R REAR SEAT	New	150.00	0.00
7	R&R REVERSE SENSOR	New	100.00	60.00
8	R&R REAR UNDER CARRIAGE	New	300.00	60.00
9	R&R REAR TYRE AND BALANCING	New	100.00	0.00
10	WHEEL ALIGNMENT	New	180.00	60.00
11	CHECK WIRING	New	100.00	30.00
12	UPHOLSTERY	New	300.00	0.00
13	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
14	CONDUCT WATER LEAK TEST	New	180.00	0.00
15	PANEL BEAT	New	2,000.00	1,000.00
16	RUST PROOFING	New	200.00	0.00
17	SPRAY PAINT	New	2,000.00	1,000.00
Gross Labour Cost (\$\$)			6,660.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >