

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21003640/AVF3Q2
Date: 08/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00043142100
Claimant Vehicle No :	SMY3210F	Insured Vehicle No :	SBL1064Y
Date of Loss:	16/03/2021	Nature of Claim:	TP
			Claim No: SNM21D201513/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY3210F		
Make & Model:	MAZDA 2, 1.5 (A)	Engine No:	P520648151
Reg. Date:	26/02/2021 (Man. Year: 2019)	Chassis No:	DJLFS703375
Colour:	Red	Odometer:	916 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,871.40	17,745.00	6,126.40	25.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,220.00	4,270.00	1,950.00	31.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	30,091.40	22,015.00	8,076.40	26.84
+ GST 7.00/7.00% (S\$)	2,106.40	1,541.05	565.35	26.84

Nett Amount (S\$)**32,197.80****23,556.05****8,641.75****26.84**INSPECTION

Date of Assignment: 22/03/2021

Date Inspected: 22/03/2021

Estimated Period of Repair: 21.0 days

Inspected At:

BW Workshop Services Pte Ltd (HQ)
291 Kaki Bukit Avenue 1, Shun Li Industrial Park
Singapore 416080**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2021)
Parts:	143	MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY3210F)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER RETAINER LH	Necessary	98.00 FL	*98.00 FL
2	2		*REAR BUMPER STAY (LOWER BRACKET) (LH & RH)	Distorted	52.00 FL	*52.00 FL
3	1		*REAR BUMPER	Distorted	1,424.00 FL	*1,424.00 FL
4	2		*SPRING (REAR BUMPER REFLECTOR) (LH & RH)	Cracked	196.00 FL	*196.00 FL
5	1		*SPLASH SHIELD (LH)	Torn	64.00 FL	*64.00 FL
6	1		*REAR FENDER LOWER PANEL (LH)	Repair	89.00 FL	*- FL
7	1		*REAR END PANEL	Distorted	513.00 FL	*513.00 FL
8	2		*BONNET HINGE (LH & RH)	Bent	170.00 FL	*170.00 FL
9	1		*BONNET	Distorted	1,029.00 FL	*1,029.00 FL
10	1		*WEATHERSTRIP (BONNET MOULDING)	Cut	128.00 FL	*128.00 FL
11	1		*BONNET LOCK PROTECTOR (COVER)	Damaged	65.00 FL	*65.00 FL
12	1		*BONNET LOCK	Damaged	182.00 FL	*182.00 FL
13	1		*FRONT BUMPER LANE FACE (REINFORCEMENT)	Bent	389.00 FL	*389.00 FL
14	1		*FRONT BUMPER FOAM (SPONGE)	Cracked	90.00 FL	*90.00 FL
15	1		*FRONT BUMPER SET PLATE (PLASTIC COVER)	Distorted	88.00 FL	*88.00 FL
16	1		*GROMMET	Necessary	30.00 FL	*30.00 FL
17	1		*FRONT BUMPER BRACKET (LH)	Bent	78.00 FL	*78.00 FL
18	1		*LOCATION TURBINE	Not Necessary	20.00 FL	*- FL
19	1		*FRONT BUMPER BRACKET (LH)	Damaged	68.00 FL	*68.00 FL
20	1		*FRONT BUMPER BRACKET (LH) (NO.2)	Damaged	68.00 FL	*68.00 FL
21	1		*FRONT BUMPER RETAINER LH	Damaged	89.00 FL	*89.00 FL
22	1		*FRONT BUMPER RETAINER RH	Not Necessary	89.00 FL	*- FL
23	1		*FRONT BUMPER PROTECTOR (LH)	Damaged	98.00 FL	*98.00 FL
24	1		*FRONT BUMPER PROTECTOR (RH)	Not Necessary	98.00 FL	*- FL
25	1		*FRONT UNDERCOVER	Deformed	128.00 FL	*128.00 FL
26	1		*BUMPER STIFFENER	Damaged	180.00 FL	*180.00 FL
27	1		*SHRACD PANEL	Distorted	583.00 FL	*583.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*ROCK STAY	Damaged	150.00 FL	*150.00 FL
29	4		*RIVET	Necessary	48.00 FL	*48.00 FL
30	4		*SPLASH SHIELD RIVET	Necessary	40.00 FL	*40.00 FL
31	1		*RADIATOR GRILL	Smashed	363.00 FL	*363.00 FL
32	1		*RADIATOR GRILL BRACKET	Cracked	91.00 FL	*91.00 FL
33	1		*FRONT MOLDING (RH)	Cracked	279.00 FL	*279.00 FL
34	1		*FRONT BUMPER LOWER MOLDING BLACK	Damaged	110.00 FL	*110.00 FL
35	1		*FRONT MOLDING (LH)	Damaged	279.00 FL	*279.00 FL
36	1		*RADIATOR COWLING	Cracked	229.00 FL	*229.00 FL
37	1		*RADIATOR	Bent	1,131.00 FL	*1,131.00 FL
38	1		*LIQUID TANK	Deformed	136.00 FL	*136.00 FL
39	2		*REAR LICENSE LAMP	Cracked	116.00 FL	*116.00 FL
40	1		*END PANEL INNER GARNISH	Deformed	82.00 FL	*82.00 FL
41	2		*FRONT HEADLAMP (LH & RH)	Cracked	4,070.00 FL	*4,070.00 FL
42	1		*FRONT AIR CLEANER (TOP)	Cracked	70.00 FL	*70.00 FL
43	1		*FRONT AIR CLEANER (BOTTOM)	Cracked	70.00 FL	*70.00 FL
44	1		*FRONT AIR DUCK	Deformed	1,007.00 FL	*130.00 FL
45	1		*REAR AIR CLEANER (LH)	Deformed	52.00 FL	*52.00 FL
46	1		*REAR AIR DUCK (LH)	Deformed	755.00 FL	*130.00 FL
47	1		*REAR DRIVING ASSIST SENSOR COVER	Not Necessary	209.00 FL	*- FL
48	2		*FRONT HEADLAMP BRACKET (LH & RH)	Cracked	140.00 FL	*140.00 FL
49	1		*FRONT FENDER (LH & RH)	N/S Buckled / O/S Repair	1,442.00 FL	*721.00 FL
50	1		*FRONT FENDER INNER SHIELD (LH & RH)	N/S Torn	240.00 FL	*120.00 FL
51	1		*AIRCON CONDENSER	Dented	650.00 FL	*650.00 FL
52	1		*FRONT WIPER COWLING (CENTER)	Not Necessary	179.00 FL	*- FL
53	2		*FRONT WIPER COWLING (LH & RH)	Not Necessary	202.00 FL	*- FL
54	1		*WEATHERSTRIP (REAR BOOT)	Cut	172.00 FL	*172.00 FL
55	1		*REAR BOOT LOCK	Jammed	198.00 FL	*198.00 FL
56	1		*REAR SPARE TYRE TRAY	Buckled	844.00 FL	*844.00 FL
57	1		*REAR SPARE TYRE BOARD	Not Necessary	278.00 FL	*- FL
58	1		*REAR SPARE TYRE SPONGE	Deformed	153.00 FL	*153.00 FL
59	1		*REAR FENDER (LH)	Repair	933.00 FL	*- FL
60	1		*REAR FENDER INNER SHIELD (LH)	Deformed	241.00 FL	*241.00 FL
61	1		*REAR FENDER TRIM BOARD (LH)	Not Necessary	269.00 FL	*- FL
62	1		*FRONT BUMPER	Distorted	2,550.00 FL	*1,350.00 FL
63	1		*REAR TAIL LAMP (LH)	Not Necessary	742.00 FL	*- FL
64	1		*REAR TAIL LAMP BRACKET (LH)	Not Necessary	52.00 FL	*- FL
65	1		*REAR EXHAUST	Not Necessary	830.00 FL	*- FL
66	1		*FRONT DOOR (LH) (NPA)	Repair	0.00 FL	*- FL
67	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
68	10		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
69	1		*FRONT TOWING HOOK COVER (TOW COVER)	Necessary	68.00 FS	*68.00 FS
70	1		*FRONT MASCOT (FRONT LOGO)	Necessary	89.00 FS	*89.00 FS
71	1		*ULTRASONIC SENSOR 2WAY (REAR SENSOR -CENTER) (NO.1)	Damaged	160.00 FS	*160.00 FS
72	1		*ULTRASONIC SENSOR 2WAY (REAR SENSOR -SIDE) (NO.2)	Damaged	150.00 FS	*150.00 FS
73	4		*RETAINER (REAR SENSOR COVER)	Necessary	80.00 FS	*80.00 FS
74	1		*SHORT CODE (REAR SENSOR WIRE)	Damaged	157.00 FS	*157.00 FS
75	1		*BRACKET (LH) (FRONT SENSOR BRACKET)	Damaged	20.00 FS	*20.00 FS
76	1		*BRACKET (RH) (FRONT SENSOR BRACKET)	Damaged	20.00 FS	*20.00 FS
77	1		*FRONT SENSOR (2 WAY)	Damaged	300.00 FS	*300.00 FS
78	1		*FRONT SENSOR WIRE	Damaged	92.00 FS	*92.00 FS
79	1		*REVERSE CAMERA	Damaged	338.00 FS	*338.00 FS
80	1		*REAR TOWING CAP	Deformed	60.00 FS	*60.00 FS
81	2		*NUMBER PLATE WITH COVER (FRONT & REAR)	Cracked	90.00 FS	*90.00 FS
82	1		*INTAKE MANIFOLD	Cracked	1,450.00 FL	*1,450.00 FL
83	1		*BATTERY TRAY (BRACKET)	Deformed	250.00 FL	*250.00 FL
84	1		*AIR FILTER	Damaged	140.00 FL	*140.00 FL
85	1		*SPARE TYRE UNDER COVER	Deformed	140.00 FL	*140.00 FL
86	1		*REAR BUMPER REFLECTOR LH	Cracked	90.00 FL	*90.00 FL
87	1		*BONNET STICK CLIP	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	29,387.00	21,754.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,515.60	4,009.00
Total Parts (\$\$)	23,871.40	17,745.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIT AND TO RENEW AFFECTED PARTS	New	3,000.00	2,200.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1,600.00	1,600.00
3	TO REMOVE AND REFIT FRONT SENSOR	New	100.00	50.00
4	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE AND REFIT REVERSE CAMERA	New	100.00	50.00
6	TO REMOVE AND REFIT EXHAUST SILENCER BOX	New	120.00	0.00
7	TO CONDUCT FRONT & REAR WHEEL ALIGNMENT TEST	New	200.00	0.00
8	TO DISMANTLE AND CHECK FRONT AND REAR UNDERCARRIAGES .TO REPLACE AFFECTED PORTIONS	New	240.00	0.00
9	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS	New	120.00	0.00
10	TO REMOVE FRONT INSTRUMENT PANEL AND REWIRING TO FACILITATE REPAIR WORKS	New	120.00	0.00
11	TO APPLY UNDERSEALING	New	100.00	100.00
12	TO REMOVE AIRCON CONDENSER ,PIPES AND DRIERS ,VACUUM AND RECHARGE GAS	New	100.00	100.00
13	TO FOCUS HEADLAMPS AND TAILLAMPS TO CHECK FRONT AND REAR LIGHTING OPERTATION AND REWIRING	New	200.00	60.00
14	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY FLATBED OR KINGS DOLLY TOWING	New	120.00	60.00
Gross Labour Cost (\$\$)			6,220.00	4,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >