

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003644/KRA3Q2
Date: 13/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070148235
Claimant Vehicle No :	SDD131L	Insured Vehicle No :	SLB1369C
Date of Loss:	18/03/2021	Nature of Claim:	TP
		Claim No:	6961573871SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDD131L	Engine No:	MR20119956C
Make & Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Chassis No:	JN1JANT32Z0010347
Reg. Date:	29/11/2017 (Man. Year: 2017)	Odometer:	101827 km
Colour:	Metallic Black		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R19	Rear Tyre Size:	225/55 R19
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,620.59	3,543.75	7,076.84	66.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,380.00	820.00	37.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,820.59	4,923.75	7,896.84	61.59
+ GST 7.00/7.00% (S\$)	897.44	344.66	552.78	61.60

Nett Amount (S\$)	13,718.03	5,268.41	8,449.62	61.59
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,670.41		

INSPECTION

Date of Assignment: 22/03/2021

Date Inspected: 23/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	4,380.00 FL	*- FL
2	1		*TAILGATE TRIM	Serviceable	474.10 FL	*- FL
3	1		*TAILGATE EMBLEM	Necessary	76.10 FL	*76.10 FL
4	1		*TAILGATE XTRAIL LOGO	Necessary	110.00 FL	*110.00 FL
5	1		*TAILGATE INNER LOCK	Repair	613.70 FL	*- FL
6	1		*REAR BUMPER	Buckled	693.10 FL	*693.10 FL
7	2		*REAR BUMPER SIDE RETAINER LH & RH	Cracked	92.20 FL	*92.20 FL
8	15		*REAR BUMPER CLIPS	Necessary	76.50 FL	*76.50 FL
9	1		*REAR BUMPER CHROME MOULDING	Cracked	171.00 FL	*171.00 FL
10	1		*REAR BUMPER CTR CVR	Serviceable	129.30 FL	*- FL
11	1		*REAR BUMPER SILVER COVER	Bent	56.50 FL	*56.50 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	569.20 FL	*569.20 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKET LH & RH	Bent / Distorted	391.20 FL	*391.20 FL
14	2		*REAR FENDER WHEEL ARCH LH & RH	Buckled	370.60 FL	*370.60 FL
15	1		*REAR WINDSCREEN MOULDING LWR	Not Necessary	84.10 FL	*- FL
16	1		*REAR END PANEL	Repair	499.30 FL	*- FL
17	1		*REAR BUMPER TOP BRACKET	Bent	782.50 FL	*782.50 FL
18	1		*REAR EXHAUST PIPE	Repair	1,244.30 FN	*- FN
19	2		*REAR EXHAUST PIPE MOUNTING	Serviceable	29.80 FN	*- FN
20	2		*REVERSE SENSOR CTR	Shorted	488.00 FN	*244.00 FN
21	1		*INNER SEAL	Not Necessary	20.00 FS	*- FS
22	1		*WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS
23	1		*REAR END PANEL INNER	Bent	230.20 FL	*230.20 FL
24	1		*REAR DOOR RUBBER (50%)	Cut	74.40 FL	*74.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

	Sub Total (\$\$)	11,696.10	3,937.50
	- List Item Discount on L Items 10.00/10.00% (\$\$)	987.40	369.35
	- Nett Item Discount on N Items 5.00/10.00% (\$\$)	88.11	24.40
	Total Parts (\$\$)	10,620.59	3,543.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO DISMANTLE ALL DAMAGED PARTS ,TO CUT & WELD END PANEL TO KNOCK & REPAIR SPARE TYRE PANEL ,FRONT FENDER LH INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	900.00	500.00
3	TO SPRAY TAILGATE ,TAILGATE TRIM ,REAR BUMPER ,END PANEK ,SPARE TYRE PANEL ,FRONT FENDER LH	New	1,000.00	800.00
4	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	0.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
6	TO REALIGN DISMANTLE AND REINSTALL /REPLACE EXHAUST PIPE	New	80.00	60.00
			Gross Labour Cost (S\$)	2,200.00
				1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >