

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003647/URA3Q2
Date: 10/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070051474
Claimant Vehicle No :	JSR1438	Insured Vehicle No :	SMT1599Z
Date of Loss:	17/03/2021	Nature of Claim:	TP
		Claim No:	9614651812SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JSR1438		
Make & Model:	HONDA FS150F, 149cc	Engine No:	KC27E2119303
Reg. Date:	17/03/2018 (Man. Year: 2018)	Chassis No:	PMKKC2760JB106450
Colour:	Red/White	Odometer:	74320 km
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	90-80-17	Rear Tyre Size:	110-70-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,761.00	721.00	1,040.00	59.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	430.00	230.00	200.00	46.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,191.00	951.00	1,240.00	56.60
Approved Total (Overridden) (S\$)		750.00		

Nett Amount (S\$)	2,191.00	750.00	1,441.00	65.77
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
Nett Liability (S\$)		810.00		

INSPECTION

Date of Assignment: 22/03/2021

Date Inspected: 22/03/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REAR SIGNALS	Cracked	160.00 FL	*160.00 FL
2	1		*REAR SWING ARM	Serviceable	300.00 FL	*- FL
3	1		*REAR RIM	Repair	420.00 FL	*- FL
4	1		*REAR RIM SHAFT	Not Necessary	60.00 FL	*- FL
5	1		*REAR RIM BEARING	Not Necessary	90.00 FL	*- FL
6	1		*REAR RIM BRAKE DISC	Not Necessary	175.00 FL	*- FL
7	1		*REAR TAILLAMP	Cracked	250.00 FL	*250.00 FL
8	1		*REAR FENDER	Broken	180.00 FL	*180.00 FL
9	1		*EXHAUST PROTECTOR FRONT	Not Necessary	105.00 FL	*- FL
10	1		*EXHAUST END CAP COVER	Cut	85.00 FL	*85.00 FL
11	1		*REAR NUMBER PLATE LAMP	Scratched	115.00 FL	*115.00 FL
12	1		*REAR NUMBER PLATE	Bent	15.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,955.00	800.00
- List Item Discount on L Items 10.00/10.00% (\$)	194.00	79.00
Total Parts (\$)	1,761.00	721.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	50.00
2	TO PROVIDE LABOUR	New	380.00	180.00
Gross Labour Cost (S\$)			430.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >