

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21003652/T1TF3E2

Date: 11/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900112739
Claimant Vehicle No : SBS6121X Insured Vehicle No : SMM5033A
Date of Loss: 18/03/2021 Nature of Claim: TP Claim No: 2692051502SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6121X**
Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A) Engine No: 90292609015757
Reg. Date: 10/10/2011 (Man. Year: 2011) Chassis No: WEB62808323122046
Colour: Multi-colour Odometer: 730902 km
Engine Capacity: 6374 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,738.00	2,738.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	3,000.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,738.00	5,738.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	401.66	401.66	0.00	0.00
Nett Amount (S\$)	6,139.66	6,139.66	0.00	0.00

INSPECTION

Date of Assignment: 22/03/2021
Date Inspected: 22/03/2021 Inspected At: Sbs Transit Ltd (Bedok) (HQ)
1470 BEDOK NORTH AVE 4
Singapore 489946
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIGNAL LED LIGHT;AMBER	Cracked	36.00 F	*36.00 F
2	1		*BUFFER	Distorted	33.00 F	*33.00 F
3	2		*REENAIL	Necessary	2.00 F	*2.00 F
4	1		*TAILPIPE	Bent	1,277.00 F	*1,277.00 F
5	1		*FACE BAR.REAR BUMPER.L/RR FOGLAMP.N/S	Cracked	364.00 F	*364.00 F
6	1		*BRACKET LH;RR BUMPER	Bent	16.00 F	*16.00 F
7	2		*HEXAGON NUT;OUTSIDE FLAPS	Necessary	3.00 F	*3.00 F
8	2		*BOLT.BUMPER.REAR	Necessary	2.00 F	*2.00 F
9	4		*GROMMET;TAIL LAMP BRACKET;ELECTRICAL	Bent	15.00 F	*15.00 F
10	1		*HEXAGON HEAD BOLT M10X16MM	Necessary	6.00 F	*6.00 F
11	2		*CLEVIS PIN HEAD;RR BUMPER	Necessary	5.00 F	*5.00 F
12	1		*SCREW;SPECIAL SHAPE;RR BUMPER (NPA)	Necessary	0.00 F	*- F
13	1		*SCREW;SPECIAL SHAPE;RR BUMPER (NPA)	Necessary	0.00 F	*- F
14	1		*NUT M10	Necessary	2.00 F	*2.00 F
15	1		*HEXAGON HEAD BOLT M10X16MM	Necessary	2.00 F	*2.00 F
16	1		*CROSSMEMBER	Bent	975.00 F	*975.00 F

F=Franchise part.

Total Parts (S\$) 2,738.00 2,738.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR	New	3,000.00	3,000.00
Gross Labour Cost (\$\$)			3,000.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >