

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21003662/AGS3Q2
Date: 16/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0007747
Claimant Vehicle No :	SMV2124T	Insured Vehicle No :	SMY924Z
Date of Loss:	15/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001125

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV2124T		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B4033046
Reg. Date:	26/09/2016 (Man. Year: 2016)	Chassis No:	RU11113042
Colour:	Black	Odometer:	56868 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R16	Rear Tyre Size:	215/50 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,646.96	2,622.56	6,024.40	69.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	730.00	1,950.00	72.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,326.96	3,352.56	7,974.40	70.40
Approved Total (Overridden) (S\$)		2,600.00		

(S\$)	11,326.96	2,600.00	8,726.96	77.05
+ GST 7.00/7.00% (S\$)	792.89	182.00	610.89	77.05
Nett Amount (S\$)	12,119.85	2,782.00	9,337.85	77.05
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,939.45		
Global Sum Settlement (S\$)		2,950.00		

INSPECTION

Date of Assignment: 22/03/2021

Date Inspected: 25/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22 Autobay
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV2124T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	892.30 FL	*- FL
2	2		*BONNET HINGES	Not Necessary	137.00 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	122.30 FL	*- FL
4	2		*BONNET SIDE RUBBER MOULDING -SIDE ,LONG	Not Necessary	115.00 FL	*- FL
5	1		*BONNET LOCK	Not Necessary	98.50 FL	*- FL
6	4		*BONNET STOPPERS	Not Necessary	100.00 FL	*- FL
7	2		*BONET EMBLEMS	Not Necessary	84.00 FL	*- FL
8	1		*HEADLAMP ASSY LH	Cracked	1,810.50 FL	*1,810.50 FL
9	1		*HEADLAMP BRACKET LH	Not Necessary	70.00 FL	*- FL
10	2		*HEADLAMP SIDE TOP GARNISH	Not Necessary	130.20 FL	*- FL
11	1		*FRONT BUMPER	Torn	592.60 FL	*592.60 FL
12	1		*BUMPER SIDE RETAINER	Necessary	68.30 FL	*38.00 FL
13	1		*FRONT BUMPER LOWER	Cut	265.60 FL	*265.60 FL
14	1		*BUMPER RADIATOR GRILLE BASE	Not Necessary	341.40 FL	*- FL
15	1		*BUMPER RADIATOR GRILLE -OUTER	Not Necessary	283.40 FL	*- FL
16	1		*BUMPER GRILLE EMBLEM H LOGO	Not Necessary	43.40 FL	*- FL
17	2		*BUMPER CHROME GARNISH	Not Necessary	173.80 FL	*- FL
18	1		*BUMPER GRILLE BRACKET	Not Necessary	107.50 FL	*- FL
19	1		*BUMPER RADIATOR GRILLE LOWER	Not Necessary	68.10 FL	*- FL
20	1		*BUMPER TOP GARNISH	Not Necessary	125.00 FL	*- FL
21	1		*FOG LAMP LH	Not Necessary	427.00 FL	*- FL
22	1		*FOG LAMP BRACKET LH	Not Necessary	80.00 FL	*- FL
23	1		*FOG LAMP COVER LH	Not Necessary	75.00 FL	*- FL
24	1		*ENGINE UNDERCOVER	Not Necessary	146.80 FL	*- FL
25	1		*FRONT REINFORCEMENT	Dented	421.00 FL	*321.00 FL
26	2		*FRONT REINFORCEMENT GARNISH	Not Necessary	88.40 FL	*- FL
27	1		*SUPPORT PANEL	Not Necessary	576.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*SUPPORT PANEL AIR GRILLE	Not Necessary	113.20 FL	*- FL
29	1		*AIR INTAKE AIR DUCT -OUTER PC	Not Necessary	77.50 FL	*- FL
30	1		*HORN	Not Necessary	58.00 FL	*- FL
31	1		*AC CONDENSER	Not Necessary	568.10 FL	*- FL
32	1		*RADIATOR ASSY	Not Necessary	1,250.60 FL	*- FL
33	1		*FRONT FENDER LH	Repair	630.00 FL	*- FL
34	1		*FRONT FENDER PROTECTOR LH	Cut	213.00 FL	*213.00 FL
35	1		*FRONT FENDER COWLING LH	Not Necessary	180.00 FL	*- FL
36	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
37	1		*SET FRONT BUMPER TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
38	1		*SET FRONT REINFORCEMENT GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
39	1		*SET ENGINE UNDERCOVER CLIPS	Not Necessary	30.00 FS	*- FS
40	1		*SET FRONT FENDER CLIPS	Not Necessary	30.00 FS	*- FS
41	1		*SET FRONT NUM PLATE W CASING	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,753.70	3,270.70
- List Item Discount on L Items 20.00/20.00% (\$)	2,106.74	648.14
Total Parts (\$)	8,646.96	2,622.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN /REALIGN ACCIDENT AFFECTED PORTION	New	1,000.00	300.00
2	TO RESPRAY ACCIDENT AFFECTED PORTION	New	1,200.00	400.00
3	TO DISMANTLE ,REPLACE AND /OR REPAIR AIR CON CONDENSER & REFILL AIR CON GAS	New	150.00	0.00
4	TO DISMANTLE ,REPLACE AND /OR REPAIR RADIATOR AND PRESSURE TEST	New	150.00	0.00
5	TO CHECK WIRING /WIRE CONNECTOR AND REWIRE /REPAIR	New	100.00	0.00
6	TO CHECK AND REALIGN HEADLAMP	New	80.00	30.00
Gross Labour Cost (\$\$)			2,680.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >