



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV18871/SUBRAMANIAN SENTHIL KUMAR Reg No/Reg Date SMY3173D / 26/02/202 Date In/Mileage 22/03/2021/ 0 Chassis No MMBSTA13AMH002993 Engine No 3A92UJT9423 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	22/03/2021/ 13:46	QUK	282 / Kevin Leong	64300				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000 REPALCE REAR' BUMPER, BOOT, END' PANEL, LH TAIL LAMP PANEL, 6 x 450					2700			4050.00	
2 REAR LH FENDER & AFFECTED AREA REPAIR ON REAR SPARE TYRE PANEL & REAR RH' FENDER					1925			2450.00	
E PNT98000 PAINT WORK ON REAR' BUMPER, REAR' BOOT, END' PANEL, SPARE TYRE PANEL, 5-5 x 350					80			120.00	
REAR LH TAIL LAMP PANEL & BOTH REAR FENDER								240.00	
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST								80.00	
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN FOR FACILITATE REPAIR								120.00	
M SUNDRY TO APPLY WINDSCREEN SEALANT								120.00	
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								80	120.00
E PNT88000 REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR (photo)					40			80.00	
M SUNDRY TO APPLY BODY SEALANT ON AFFECTED AREA								450.00	
M SUNDRY PERFORM RUST PREVENTION								30.00	
A 13900099 REMOVE & INSTALL REAR FUEL TANK FOR FACILITATE REPAIR (photo)								120.00	
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								50.00	
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					30			50.00	
M SUNDRY TO SUPPLY C & C EMBLEM nec								120.00	
M SUNDRY TO SUPPLY 'MIVEC' EMBLEM									
E PNT88000									

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-B500111-X

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
Contact No 6419 1892

Owner Name & Vehicle Info

Cust No/Name KCV18871/SUBRAMANIAN SENTHIL KUMAR
Reg No/Reg Date SMY3173D / 26/02/202
Date In/Mileage 22/03/2021/ 0
Chassis No MMR5TA13AMH002993
Engine No 3A92UJT9423
Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31)
Colour/Trim UOI TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	22/03/2021/ 13:46	QUK	282 / Kevin Leong	64300

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TO TRANSFER REAR BOOT COMPARTMENTS TO NEW PANEL				50.00 X
M SUNDRY				
TO SUPPLY REAR NUMBER PLATE WITH FRAME				220.00 X
M SUNDRY				
TO SUPPLY REAR REVERSE SENSOR <i>Shrtd</i>				30 50.00
M SUNDRY				
SUNDRIES				120.00 X
A WHEELALIGNMENTBP				
To Conduct Computerize Full Wheel Alignment				
M REFLECTOR,LH	1.00	48.00	23.00	36.96
M LAMP ASSY,LICENSE PLATE	1.00	51.00	23.00	39.27
M LAMP ASSY,COMB,RR LH	1.00	509.00	23.00	391.93
M BRACKET,RR BUMPER,LH	1.00	28.00	23.00	21.56
M FACE,RR BUMPER	1.00	654.00	23.00	503.58
M BRACKET,RR BUMPER,RH	1.00	28.00	23.00	21.56
M PANEL,QTR,OTR LH	1.00	808.00	23.00	622.16
M PANEL,RR COMB LAMP HSG,LH	1.00	60.00	23.00	46.20
M EXTN,QTR PANEL,UPR OTR LH	1.00	118.00	23.00	90.86
M PANEL,RR END	1.00	427.00	23.00	328.79
M STOPPER,WINDSHIELD GLASS	2.00	3.00	23.00	4.62
M GLASS,RR WINDOW	1.00	544.00	23.00	418.88
M SPACER,RR WINDOW	3.00	9.00	23.00	20.79
M WEATHERSTRIP,TRUNK LID	1.00	157.00	23.00	120.89
M PANEL,TRUNK LID	1.00	795.00	23.00	612.15
M HINGE,TRUNK LID,LH	1.00	203.00	23.00	156.31
M HINGE,TRUNK LID,RH	1.00	203.00	23.00	156.31
M LATCH,TRUNK LID	1.00	218.00	23.00	167.86
M SHIELD,RR WHEELHOUSE,LH	1.00	40.00	23.00	30.80
M MUD GUARD,RR LH	1.00	35.00	23.00	26.95
M GARNISH,RR END PANEL	1.00	336.00	23.00	258.72
M MARK,THREE-DIA	1.00	70.00	23.00	53.90
M MARK,ATTRAGE	1.00	21.00	23.00	16.17
M TRIM,RR END	1.00	66.00	23.00	50.82

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV18871/SUBRAMANIAN SENTHIL KUMAR Reg No/Reg Date SMY3173D / 26/02/202 Date In/Mileage 22/03/2021/ 0 Chassis No MMBSTA13AMH002993 Engine No 3A92UJT9423 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/03/2021/ 13:46	QUK	282 / Kevin Leong	64300			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BOARD, TRUNK ROOM FLOOR ✓ TAI					1.00	195.00	23.00	150.15

Estimate

Steve (CLKK) 22/3/21, 2.00pm

OD - NH AL

EX - ?

P/P

My BOL 21

17 ~~14~~ days

- LHK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	12,988.19
7% GST on	12988.19	909.17
Total Payable		13,897.36

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.