LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21003675/T1VF3E2

Date: 05/05/2021

MS010158

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No:

Claimant Vehicle SHC8400R Insured Vehicle No: SJP1301Y

Date of Loss: 21/03/2021 Nature of Claim: TP Claim No: M2101360

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC8400R

Make & Model: HYUNDAI I40, 1.7 D CRDi (A) Engine No: D4FDFU537829

Reg. Date: 06/08/2015 (Man. Year: 2015) Chassis No: KMHLB41UMGU076905

Colour: Blue Odometer: 491905 km

Engine Capacity: 1685 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,587.38	1,334.80	1,252.58	48.41
Miscellaneous Items		11.00	11.00	0.00	0.00
Labour		840.00	620.00	220.00	26.19
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,438.38	1,965.80	1,472.58	42.83
	Approved Total (Overridden) (S\$)		1,500.00		
	(S\$)	3,438.38	1,500.00	1,938.38	56.37
	+ GST 7.00/7.00% (S\$)	240.69	105.00	135.69	56.38
	Nett Amount (S\$)	3,679.07	1,605.00	2,074.07	56.37

INSPECTION

Date of Assignment: 22/03/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 23/03/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 May 2021)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC8400R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. F	Particulars	Condition	Repairer's	Reference	Amount
1	1	*	*REAR BUMPER	Deformed	1,106.00 FL	-	*1,106.00 FL
2	1	*	*REAR BUMPER UNDER COVER	Cracked	228.00 FL	-	*228.00 FL
3	1	*	*REAR BUMPER REINFORCMENT	Not Necessary	428.40 FL	-	*- FL
4	10	*	*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
5	1	*	*REVERSE SENSOR	Not Necessary	135.70 F	-	*- F
6	2	*	*REAR FENDER ADVERTISEMENT STICKER RH/LH	Necessary	200.00 F	-	*200.00 F
7	1	*	*REAR BUMPER ADVERTISEMENT STICKER	Cut	50.00 F	-	*50.00 F
8	1	*	*EXHAUST MUFFLER LH	Not Necessary	967.70 FL	-	*- FL
F=Fra	ınchise	part. L=ListIte	emDisc.				
				Sub Total (S\$)	3,137.80	1,606.00	
			- List Item Discount on L Items 20.	.00/20.00% (S\$)	550.42	271.20	
				Total Parts (S\$)	2,587.38		1,334.80
			Report was unsubmitted during this pr	int-out.	,		7

Recommended Miscellaneous Items

No Q1	ty Particulars		Repairer's	Amount			
Miscellaneous Items							
1 1	OD/TP Case (Insurer)		11.00	11.00			
		Sub Total (S\$)	11.00	11.00			

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	300.00	280.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I EXHAUST SYSTEM	New	120.00	0.00
4	R/I REVERSE SENSOR	New	120.00	30.00
5	TOW FEE	New	-	60.00
		Gross Labour Cost (S\$)	840.00	620.00
	Re	port was unsubmitted during this print-out.		

< END OF ESTIMATES >