

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21003679/UPS3Q2**Date:** 17/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100383394-06
<b>Claimant Vehicle No :</b>	SMM9946P	<b>Insured Vehicle No :</b>	SKP3051T
Date of Loss:	22/03/2021	Nature of Claim:	TP
		Claim No:	2889323414SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMM9946P</b>	Engine No:	L13B1461135
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK31351126
Reg. Date:	23/07/2019 (Man. Year: 2019)	Odometer:	19709 km
Colour:	Grey		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,157.60	1,160.88	4,996.72	81.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,360.00	740.00	35.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,257.60</b>	<b>2,520.88</b>	<b>5,736.72</b>	<b>69.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	8,257.60	2,000.00	6,257.60	75.78
<b>+ GST 7.00/7.00% (S\$)</b>	578.03	140.00	438.03	75.78
<b>Nett Amount (S\$)</b>	<b>8,835.63</b>	<b>2,140.00</b>	<b>6,695.63</b>	<b>75.78</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,442.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,400.00</b>		

INSPECTION

Date of Assignment:	22/03/2021	
Date Inspected:	22/03/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	68.10 F	*- FL
2	1		*TAILGATE	Not Necessary	845.20 F	*- FL
3	1		*TAILGATE FIT EMBLEM	Not Necessary	45.00 F	*- FL
4	1		*TAILGATE INNER LOCK	Not Necessary	209.60 F	*- FL
5	1		*TAILGATE INNER TRIM	Not Necessary	388.20 F	*- FL
6	1		*TAILGATE WEATHERSTRIP	Not Necessary	166.80 F	*- FL
7	1		*REAR BUMPER	Dented / Deformed	645.50 F	*585.20 FL
8	2		*REAR BUMPER SIDE RETAINERS	Serviceable	61.00 F	*- FL
9	1		*REAR BUMPER LOWER MOULDING O/S	Cracked	145.00 F	*86.20 FL
10	1		*REAR END PANEL	Bent / Cracked	366.00 F	*345.20 FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	219.00 F	*- FL
12	1		*TAILLAMPS	O/S Cracked	970.00 F	*322.00 FL
13	2		*TAILLAMP HOUSING PANELS	Not Necessary	577.00 F	*- FL
14	1		*REAR FENDER	Not Necessary	911.20 F	*- FL
15	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
16	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	280.00 FS	*- FS
17	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
18	1		*SET REAR BUMPER REFLECTOR	Not fitted	120.00 FS	*- FS
19	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,157.60	1,428.60
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	267.72
Total Parts (S\$)	6,157.60	1,160.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO TRANSFER TAILGATE COMPONENTS	New	100.00	0.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
6	TO SPRAY RUST PROOFING	New	100.00	30.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	700.00	580.00
8	TO PUTTY & SPRAY PAINTING	New	800.00	600.00
<b>Gross Labour Cost (\$)</b>			<b>2,100.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >