

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003681/BGS3Q2
Date: 18/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800043835	
Claimant Vehicle No :	SMY6420X	Insured Vehicle No :	SLN4531S	
Date of Loss:	19/03/2021	Nature of Claim:	TP	Claim No: 0330209297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY6420X		
Make & Model:	MERCEDES-BENZ GLB200, 1.3 AMG LINE PREMIUM PLUS (A)	Engine No:	28291480312687
Reg. Date:	18/03/2021 (Man. Year: 2020)	Chassis No:	W1N247682W050292
Colour:	Black	Odometer:	234 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R19	Rear Tyre Size:	235/50 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,334.57	6,688.03	20,646.54	75.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,080.00	2,460.00	3,620.00	59.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,414.57	9,148.03	24,266.54	72.62
Approved Total (Overridden) (S\$)		7,300.00		

(S\$)	33,414.57	7,300.00	26,114.57	78.15
+ GST 7.00/7.00% (S\$)	2,339.02	511.00	1,828.02	78.15
Nett Amount (S\$)	35,753.59	7,811.00	27,942.59	78.15
+ Car Rental (9.0 x S\$100.00/day + 7.00% GST) (S\$)		963.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,781.45		

INSPECTION

Date of Assignment: 22/03/2021

Date Inspected: 22/03/2021

Estimated Period of Repair: 7.0 days

Inspected At:

160 SIN MING DRIVE #01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,986.39 FL	*- FL
2	1		*TAILGATE LOGO	Necessary	110.00 FL	*92.00 FL
3	1		*TAILGATE EMBLEM GLB 200	Necessary	198.00 FL	*120.00 FL
4	1		*TAILGATE INNER LOCK	Not Damaged	384.60 FL	*- FL
5	1		*TAILGATE INNER LOCK STRIKER	Not Damaged	88.00 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Not Damaged	498.00 FL	*- FL
7	1		*TAILGATE WINDSCREEN MOULDING	Not Damaged	314.55 FL	*- FL
8	1		*REAR BUMPER	Broken	1,858.00 FL	*1,350.00 FL
9	1		*REAR BUMPER LOWER	Broken	983.35 FL	*775.00 FL
10	1		*REAR BUMPER CHROME DIFUSSER	Broken	788.65 FL	*729.14 FL
11	1		*REAR BUMPER INNER SPONGE	Not Necessary	325.60 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Dented	851.33 FL	*795.00 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	304.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	371.20 FL	*150.00 FL
15	1		*REAR BUMPER OUTER CHROME GARNISH	Broken	441.60 FL	*190.00 FL
16	2		*REAR BUMPER BRACKET	No such part	291.64 FL	*- FL
17	2		*REAR BUMPER ARCH GARNISH	Not Damaged	799.50 FL	*- FL
18	1		*REAR BUMPER REFLECTOR	O/S Broken	196.00 FL	*65.00 FL
19	1		*REAR BUMPER CENTRE BEAM	Broken	383.00 FL	*230.00 FL
20	1		*REAR BUMPER LOWER CENTRE COVER	Broken	428.79 FL	*305.00 FL
21	1		*REAR BUMPER TOW COVER	Dislodged	185.00 FL	*50.00 FL
22	4		*REAR BUMPER REVERSE SENSOR	Scratched (2 PCS ONLY)	983.20 FL	*380.00 FL
23	1		*REAR END PANEL	Dented	2,136.60 FL	*1,840.00 FL
24	1		*REAR END PANEL TOP GARNISH	Not Damaged	425.75 FL	*- FL
25	2		*TAILLAMP	Not Damaged	2,196.00 FL	*- FL
26	2		*TAILLAMP LOWER BRACKET	Not Necessary	396.00 FL	*- FL
27	1		*REAR EXHAUST PIPE	Not Damaged	3,600.00 FL	*- FL
28	2		*REAR EXHAUST PIPE HEATSHIELD	Not Damaged	672.00 FL	*- FL
29	2		*REAR EXHAUST PIPE CHROME COVER	Not Damaged	716.00 FL	*- FL
30	2		*FRONT HEADREST	Not Damaged	2,880.00 FL	*- FL
31	1		*AIRBAG CONTROL MODULE	Repair	1,899.00 FL	*- FL
32	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
33	1		*TAILGATE SEALANT	Not Necessary	100.00 FS	*- FS
34	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
35	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	60.00 FS	*- FS
37	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
38	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
39	1		*REAR BUMPER LOWER CLIPS	Necessary	60.00 FS	*30.00 FS
40	1		*REAR BUMPER CHROME DIFUSSER CLIPS	Necessary	60.00 FS	*30.00 FS
41	1		*REAR BUMPER OUTER CHROME GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
42	1		*REAR BUMPER ARCH GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
43	1		*REAR BUMPER LOWER CENTRE COVER CLIPS	Necessary	60.00 FS	*30.00 FS
44	4		*REAR BUMPER REVERSE SENSOR SEAL	Necessary (2 PCS ONLY)	272.00 FS	*24.00 FS
45	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
46	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
47	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS
48	2		*TAILLAMP CLIPS	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	30,203.75	7,395.14
- List Item Discount on L Items 10.00/10.00% (\$)	2,869.18	707.11
Total Parts (\$)	27,334.57	6,688.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R TAILGATE COMPONENT	New	150.00	0.00
2	R&R TAILGATE WINDSCREEN	New	250.00	0.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	R&R REAR EXHAUST PIPE	New	150.00	0.00
5	R&R FRONT SEAT HEADREST	New	300.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	CHECK WIRING	New	100.00	50.00
8	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
9	COATING	New	630.00	630.00
10	PANEL BEATING	New	1,800.00	1,000.00
11	RUST PROOFING	New	200.00	0.00
12	SPRAY PAINTING	New	1,800.00	600.00
Gross Labour Cost (\$\$)			6,080.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >