

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 8228U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER | TO REPAIR SEE LABOUR | 3,361.00 | - |
| 2 | FRONT BUMPER SIDE RETAINER L/R @\$68.50 | SERVICEABLE | 137.00 | - |
| 1 | FRONT BUMPER REINFORCEMENT | SERVICEABLE | 459.80 | <u>-</u> |
| 1 | FRONT BUMPER ENERGY ABSORBER | SERVICEABLE | 176.00 | - |
| 1 | FRONT RADIATOR SIDE AIR GUARD LH | CRACKED | 115.00 | 115.00 |
| 1 | FRONT RADIATOR GRILLE | SERVICEABLE | 2,259.00 | - |
| 1 | FRONT RADIATOR GRILLE GOLD TRIM | SERVICEABLE | 415.00 | - |
| 2 | FRONT HEADLAMP ASSY L/R @\$2138.00 | HLD CRACKED / FAULTY | 4,276.00 | 4,276.00 |
| 2 | FRONT LOWER FOG LAMP GRILLE TRIM L/R @\$321.00 | SERVICEABLE | 642.00 | _ |
| 1 | FRONT RADIATOR GRILLE EMBLEM | SERVICEABLE | 150.00 | - |
| 1 | SET FRONT BUMPER CLIPS | SERVICEABLE | 45.00 | - |
| 2 | FRONT SENSOR @\$351.00 | SERVICEABLE | 702.00 | _ |
| | LESS 10% DISCOUNT | | - | -439.10 |
| | | | 12,737.80 | 3,951.90 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET FRONT BUMPER LICENSE PLATE WITH CASING (SN) | CRACKED | 120.00 | 80.00 |
| | | | 120.00 | 80.00 |
| | LABOUR | | | |
| | SPRAY PAINTING ON ABOVE NEW & REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS. | | 800.00 | 250.00 |
| | REMOVE FRONT FITTINGS, DISMANTLE AND RENEW FRONT DAMAGED PARTS. RE-ORGANIZE FRONT AFFECTED MANAGEMENT COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER. | , | 900.00 | 200.00 |
| | TO CARRY OUT DIAGNOSTIC CHECKS, FOCUS HEADLIGHT & CENTRE LOCKING SYSTEM FOR PROPER FUNCTION. | | 250.00 | 30.00 |
| | TO REMOVE & REINSTALL FRONT SENSOR AND CHECK FOR PROPER FUNCTION. | | 120.00 | 40.00 |
| | | | 2,070.00 | 520.00 |
| | GRAND TOTAL | | 14,927.80 | 4,551.90 |

Report Ref No. CS1/LAW21003685/Gvf3e2





RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)

3,650.00

Report Ref No. CS1/LAW21003685/Gvf3e2

8

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.