

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003690/KRA3Q2
Date: 18/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210006888
Claimant Vehicle No :	SLM9408M	Insured Vehicle No :	GBK9197A
Date of Loss:	19/03/2021	Nature of Claim:	TP
		Claim No:	8733936394SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM9408M	Engine No:	3ZZ4753539
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106105103
Reg. Date:	23/04/2008 (Man. Year: 2008)	Odometer:	408376 km
Colour:	Metallic Green		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	KAPSEN 7 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 7 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,790.30	2,383.00	1,407.30	37.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,350.00	450.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,590.30	3,733.00	1,857.30	33.22
Approved Total (Overridden) (S\$)		2,950.00		

(S\$)	5,590.30	2,950.00	2,640.30	47.23
+ GST 7.00/7.00% (S\$)	391.32	206.50	184.82	47.23
Nett Amount (S\$)	5,981.62	3,156.50	2,825.12	47.23
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 22/03/2021

Date Inspected: 23/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Allswell Motor Traders (HQ)
 160 Sin Ming Drive #04-05 Sin Ming Autocity
 SINGAPORE 575722

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FENDER	Bent	600.00 F	*456.00 FL
2	1		*BONNET FRONT	Bent	900.00 F	*757.20 FL
3	1		*BUMPER FRONT	Bent / Cracked	720.00 F	*485.00 FL
4	1		*LH HEADLAMP	Broken	460.00 F	*460.00 FL
5	1		*SUPPORT PANEL	Bent	500.00 F	*500.00 FL
6	1		*LH WATER TANK	Dented	190.00 F	*85.50 FL
7	1		*LH INNER SHIELD	Missing	192.00 F	*192.00 FL
8	1		*FRONT LICENSE PLATE	Missing	40.00 F	*40.00 FL
9	1		*CLIPS & RETAINER STUDS	Necessary	40.00 FS	*40.00 FS
10	1		*FRT LOWER COVER	Missing	148.30 F	*148.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,790.30	3,164.00
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	781.00
Total Parts (\$)	3,790.30	2,383.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DISMANTLE /ASSEMBLY OF ALL AFFECTED PARTS (HEADLAMP) BONNET FENDER/BUMPER/SHIELD AND ETC }	New	700.00	600.00
2	PANEL KNOCKING OF SUPPORT PANEL }	New	300.00	0.00
3	SPRAY PAINTING OF ALL AFFECTED PARTS BONNET FENDER BUMPER	New	800.00	750.00
Gross Labour Cost (\$\$)			1,800.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >