

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	Re	ef:	CS3/ASM21003692/Qtf3e2	
	8 SHENTON WAY TOWERSINGAPOR		Da	ate:	01/04/2021	
	ATTN: JOHNNY Y	ONG	Co	ode:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBF 5233G	Veh. Inspected		SGW 3941K	
	Policy No.	P2347750	Coverage (\$)		0.00	
	Claim No.	S1M035US	Excess (\$)		0.00	
	Assign From	JOHNNY YONG	Assign Date		19/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL 1.5X	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	RU11106239	Colour		BLUE	
	Odometer	90969 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	BRIDGESTONE		6 mm	
	L/H Front Tyre	215/60 R16	BRIDGESTONE		6 mm	
	R/H Rear Tyre	215/60 R16	BRIDGESTONE		6 mm	
	L/H Rear Tyre	215/60 R16	BRIDGESTONE		6 mm	
4. Description of Damages						
	HE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information					
	Accident Date	17/03/2021	Inspect Date / Tim	ne	23/03/2021 (11:27 AM)	
	Survey held at	WAH YU AUTOMOTIVE BODY V	VORK			
	176 SIN MING DRIVE #05-09 SINGAPORE 575721					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/ASM21003692/Qtf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser