

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21003698/R1qf3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA Date: 16/04/2021 **TOWERSINGAPORE 068811** ATTN: TAN JUN HONG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 3147R** Veh. Inspected SJA 6216G Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M035U9 Excess (\$) 0.00 TAN JUN HONG **Assign Date** 22/03/2021 Assign From 2. **Vehicle Particulars & Condition** TOYOTA COROLLA ALTIS 1.6 Make & Model 1598 c.c Engine No. **HIDDEN** Year of Reg. 2007 Chassis No. MR053ZEC107157390 Colour **GREY** 64548 KM Odometer IN ORDER Steering **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General **Conditions of Tyres** 3. Size Make **Balance** 215/60 R16 MICHELIN 6 mm R/H Front Tyre L/H Front Tyre 215/60 R16 **MICHELIN** 6 mm R/H Rear Tyre 215/60 R16 **MICHELIN** 6 mm 215/60 R16 **MICHELIN** L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. **General Information** 5. **Accident Date** 18/03/2021 Inspect Date / Time 22/03/2021 ( 04:32 PM ) RIGHT CLICK AUTOWORKS PTE LTD Survey held at 7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/ASM21003698/R1qf3e2

**Estimate Days of Repair** 

Inspected By

**Automotive Assessor** 

5b.

MOHAMMED RASUL BIN MOHD YUNUS

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

6 Working Days