

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003699/ARA3Q2
Date: 16/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993741
Claimant Vehicle No :	SLL5958Z	Insured Vehicle No :	SMX6676E
Date of Loss:	20/03/2021	Nature of Claim:	TP
		Claim No:	2440457089SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL5958Z		
Make & Model:	TOYOTA SIENTA, 1.5 G CVT (A)	Engine No:	2NR8636863
Reg. Date:	01/03/2017 (Man. Year: 2016)	Chassis No:	NSP1707039274
Colour:	White	Odometer:	83562 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,232.98	13,157.50	9,075.48	40.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,910.00	3,270.00	4,640.00	58.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,142.98	16,427.50	13,715.48	45.50
Approved Total (Overridden) (S\$)		13,100.00		

Nett Amount (S\$)	30,142.98	13,100.00	17,042.98	56.54
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		14,107.45		
Global Sum Settlement (S\$)		14,100.00		

INSPECTION

Date of Assignment: 22/03/2021

Date Inspected: 22/03/2021

Estimated Period of Repair: 10.0 days

Inspected At:

Smartone Auto Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	436.60 FL	*436.60 FL
2	2		*FRONT BUMPER FOG LAMP COVER GARNISH	Not Necessary	219.60 FL	*- FL
3	1		*FRONT BUMPER LOGO	Necessary	65.20 FL	*65.20 FL
4	1		*FRONT BUMPER TOP RUBBER	Not Necessary	32.70 FL	*- FL
5	1		*FRONT BUMPER BOTTOM COVER	Not Necessary	174.50 FL	*- FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	96.20 FL	*96.20 FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	374.30 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	135.60 FL	*135.60 FL
9	1		*FRONT GRILLE C/W CHROME	Cracked	832.20 FL	*596.00 FL
10	2		*FRONT FENDER INNER COWLING	Not Necessary	330.40 FL	*- FL
11	2		*HEADLAMP	Cracked	6,153.00 FL	*5,600.00 FL
12	1		*BONNET	Repair	620.70 FL	*- FL
13	1		*BONNET LOCK	Not Necessary	95.40 FL	*- FL
14	1		*BONNET LOCK BRACE PANEL	Bent	123.60 FL	*123.60 FL
15	1		*FRONT SUPPORT PANEL	Repair	989.50 FL	*- FL
16	2		*HORN	Not Necessary	252.80 FL	*- FL
17	1		*AIR CON CONDENSOR	Dented	1,299.40 FL	*1,125.00 FL
18	2		*AIR CON CONDENSOR SIDE AIR GUARD	Deformed	131.40 FL	*131.40 FL
19	1		*AIR CON CONDENSOR UPPER AIR GUARD	Deformed	179.30 FL	*179.30 FL
20	1		*RADIATOR	Not Necessary	1,693.70 FL	*- FL
21	4		*RADIATOR MOUNTING	Not Necessary	76.80 FL	*- FL
22	1		*REAR BUMPER	Deformed	466.90 FL	*466.90 FL
23	1		*REAR CENTER BUMPER (UPPER)	Deformed	186.70 FL	*186.70 FL
24	2		*REAR BUMPER REFLECTOR GARNISH	Cut	257.40 FL	*257.40 FL
25	2		*REAR BUMPER SIDE RETAINER	Necessary	139.60 FL	*139.60 FL
26	1		*REAR BUMPER CENTER SPONGE	Cracked	107.20 FL	*45.00 FL
27	2		*REAR FENDER COWLING	Not Necessary	258.20 FL	*- FL
28	2		*REAR FENDER INNER TRIM BOARD (LOWER)	Cracked	1,254.20 FL	*972.00 FL
29	2		*TAILLAMP	Cracked	1,055.80 FL	*1,055.80 FL
30	2		*TAILLAMP LOWER BRACKET	Not Necessary	91.20 FL	*- FL
31	1		*TAIL GATE	Distorted	1,323.50 FL	*1,180.00 FL
32	2		*TAIL GATE LAMP (LED)	Cracked	715.80 FL	*715.80 FL
33	2		*TAIL GATE NUMBER PLATE LAMP	Not Necessary	93.60 FL	*- FL
34	1		*TAIL GATE OUTER MOULDING	Cracked	243.70 FL	*243.70 FL
35	1		*TAIL GATE OUTER SWITCH BUTTOM	Not Necessary	314.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*TAIL GATE INNER HOLDER GARNISH	Not Necessary	28.60 FL	*- FL
37	1		*TAIL GATE LOCK	Damaged	458.70 FL	*317.00 FL
38	1		*TAIL GATE CATCH	Not Necessary	38.90 FL	*- FL
39	1		*TAIL GATE INNER TRIM	Not Necessary	578.60 FL	*- FL
40	4		*TAIL GATE STOPPER	Not Necessary	98.40 FL	*- FL
41	1		*TAIL GATE WEATHERSTRIP	Cut	325.17 FL	*325.17 FL
42	1		*TAIL GATE WIPER MOTOR	Damaged	673.40 FL	*673.40 FL
43	1		*TAIL GATE WIPER MOTOR COVER RUBBER	Not Necessary	59.80 FL	*- FL
44	1		*TAIL GATE DETECTOR	Cracked	239.10 FL	*125.00 FL
45	1		*TAIL GATE DETECTOR WIREHARNES	Not Necessary	288.90 FL	*- FL
46	3		*TAIL GATE WINDSCREEN GLASS MOULDING	Necessary	97.80 FL	*97.80 FL
47	1		*REAR END PANEL (OUTER)	Dented	696.70 FL	*696.70 FL
48	1		*REAR END PANEL (INNER)	Repair	433.80 FL	*- FL
49	1		*REAR END PANEL TOP GARNISH	Deformed	145.20 FL	*145.20 FL
50	1		*REAR STORAGE GARNISH	Deformed	344.60 FL	*344.60 FL
51	1		*REAR TOOL COVER BOARD	Not Necessary	475.10 FL	*- FL
52	1		*FRONT NUMBER PLATE (OFF PEAK PLATE)	Bent	180.00 FS	*60.00 FS
53	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
54	1		*FRONT BUMPER LOGO BASE (SPECIAL TYPE)	Necessary	150.00 FS	*60.00 FS
55	1		*SET FRONT RADIATOR GRILLE CLIP	Necessary	60.00 FS	*30.00 FS
56	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	120.00 FS	*- FS
57	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
58	1		*RADIATOR COOLANT	Not Necessary	40.00 FS	*- FS
59	1		*REAR NUMBER PLATE (OFF PEAK PLATE)	Bent	180.00 FS	*60.00 FS
60	1		*REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
61	1		*SET REAR BUMPER REFLECTOR (SPECIAL TYPE)	Not Necessary	200.00 FS	*- FS
62	1		*TAIL GATE LOGO (SPECIAL TYPE)	Necessary	150.00 FS	*60.00 FS
63	1		*SET TAIL GATE OUTER MOULDING CLIP	Necessary	80.00 FS	*20.00 FS
64	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	80.00 FS	*20.00 FS
65	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
66	1		*TAIL GATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*30.00 FS
67	1		*SET REAR FENDER INNER TRIM BOARD CLIP	Necessary	80.00 FS	*60.00 FS
68	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
69	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
70	1		*REAR END PANEL INSULATION SEAL (OUTER)	Necessary	150.00 FS	*60.00 FS
71	1		*REAR END PANEL INSULATION SEAL (INNER)	Not Necessary	150.00 FS	*- FS
72	1		*SET REAR STORAGE GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
73	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
74	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	28,683.97	17,276.67
					- List Item Discount on L Items 25.00/25.00% (S\$)	6,450.99	4,119.17
					Total Parts (S\$)	22,232.98	13,157.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,200.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	500.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
5	REFOCUS HEADLAMP BEAM	New	60.00	0.00
6	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	800.00
7	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
8	TUFF COAT	New	250.00	60.00
9	WIRING CHECK	New	80.00	30.00
10	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
13	REAR CHASSIS ALIGNMENT	New	250.00	0.00
14	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
15	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
16	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
17	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
18	REMOVE AND RESEAL OFF PEAK PLATE	New	280.00	80.00
19	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			7,910.00	3,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >