



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JKF 4834

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	MIRROR (R) (CONSISTENT)	CRACKED	40.00	40.00
1	HEAD LAMP COVER UPPER (CONSISTENT)	CRACKED	45.00	45.00
1	HEAD LAMP ASSY (CONSISTENT)	CRACKED	60.00	60.00
1	HANDLE BAR (CONSISTENT)	BENT	55.00	55.00
1	HANDLE GRIP (CONSISTENT)	DISTORTED	22.00	22.00
1	THOTAL CABLE ASSY (CONSISTENT)	NOT NECESSARY	40.00	-
1	BRAKE LEVER (CONSISTENT)	CUT	18.00	18.00
1	HEAD LAMP LOWER COVER (CONSISTENT)	CRACKED	35.00	35.00
1	SIDE COVER FRONT (R) (CONSISTENT)	CRACKED	65.00	65.00
1	FENDER (F) (CONSISTENT)	CUT	38.00	38.00
1	FOLK ASSY & STEERING COAN (CONSISTENT)	BENT	350.00	350.00
1	FRONT WHEEL ASSY (CONSISTENT)	BENT	220.00	220.00
1	DIS PLATE (ROTOR) (CONSISTENT)	BENT	120.00	120.00
1	BRAKE CILIPER ASSY (CONSISTENT)	BENT	180.00	180.00
1	FOOT BRAKE PADDLE (CONSISTENT)	BENT	40.00	40.00
1	FOOT REST RUBBER (F) (CONSISTENT)	TORN	18.00	18.00
1	FOOT REST BAR (CONSISTENT)	BENT	30.00	30.00
1	EXHAUST PIPE GUARD (CONSISTENT)	BENT	350.00	120.00
1	REAR BOX GIVI (CONSISTENT)	CUT	180.00	180.00
1	BOX BRACKET (CONSISTENT)	BENT	120.00	120.00
1	TAIL COVER (R) (CONSISTENT)	CRACKED	38.00	38.00
1	TAIL COVER (CENTER) (CONSISTENT)	CRACKED	18.00	18.00
1	TAIL COVER (L) (CONSISTENT)	CUT	38.00	38.00
1	NUMBER PLATE (CONSISTENT)	NECESSARY	20.00	20.00
	LESS 10% DISCOUNT		-	-187.00
			2,140.00	1,683.00
LABOUR				
	WORKMANSHIP STRIPS FIX BODY PARTS.		280.00	200.00

Report Ref No. CS/ASM21003700/T1f3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING SERVICE.		60.00	60.00
			340.00	260.00
	GRAND TOTAL		2,480.00	1,943.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,550.00

Report Ref No. CS/ASM21003700/T1f3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.