



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: TAN JUN HONG		Ref: CS/ASM21003700/T1f3e2 Date: 27/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 1330R	Veh. Inspected	JKF 4834
Policy No.		Coverage (\$)	0.00
Claim No.	S1M035YM	Excess (\$)	0.00
Assign From	TAN JUN HONG	Assign Date	19/03/2021
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	GREEN
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90 R17	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90 R17	PIRELLI	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/03/2021	Inspection Date	22/03/2021
Survey held at	FIRST MOTOR BLK 3006 UBI RD 1 #01-398 SINGAPORE 408700		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	