



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 5802D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	FORK INNER TUBES	SERVICEABLE	440.00	-
2	FORK OUTER TUBES	NOT NECESSARY	460.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	245.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING	NOT NECESSARY	42.00	-
1	FRONT FENDER	CUT	76.00	76.00
1	HEADLAMP	CRACKED	450.00	295.00
1	LAMP STAY	NOT NECESSARY	120.00	-
1	HANDLE-BAR	BENT	150.00	150.00
1	HANDLE-BAR BALANCER	CUT	68.00	68.00
1	SET HANDLE-BAR GRIP	NOT NECESSARY	85.00	-
1	CLUTCH LEVER	SCRATCHED	35.00	35.00
1	MASTER PUMP	NOT NECESSARY	285.00	-
1	FUEL TANK SIDE COVER - L/H	CUT	250.00	190.00
1	TOP COWLING	CRACKED	180.00	180.00
1	SIDE STAND	NOT NECESSARY	95.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	135.00	-
2	FRONT FOOTREST	N/S CUT	96.00	48.00
2	FRONT FOOTREST BRACKETS	NOT NECESSARY	220.00	-
1	GEAR PEDAL	CUT	58.00	58.00
2	REAR TAILBOARD - L/R/H	CUT	185.00	185.00
2	REAR SIGNAL LAMPS	NOT NECESSARY	160.00	-
1	REAR FENDER - INNER	DEFORMED	160.00	122.00
1	REAR FENDER - OUTER	DISTORTED	110.00	90.00
1	REAR SHOCK ABSORBER	NOT NECESSARY	220.00	-
1	SWING ARM	BENT / TWISTED	420.00	420.00
1	CHAIN COVER	NOT NECESSARY	52.00	-
1	REAR TAILLAMP	BROKEN	220.00	180.00
1	REAR CENTRE COWLING	CUT	95.00	95.00
1	REAR SPORT RIM	NOT NECESSARY	480.00	-

Report Ref No. CS/UOI21003710/Utf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RIM SHAFT	NOT NECESSARY	52.00	-
1	BRAKE SHAFT	NOT NECESSARY	48.00	-
1	REAR RIM BEARING	NOT NECESSARY	58.00	-
	LESS 10% DISCOUNT		-579.50	-219.20
			5,215.50	1,972.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET NUMBER PLATE (SN)	REAR BENT	28.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	85.00	-
1	E.R.P. IU (SN)	SERVICEABLE	180.00	-
1	REAR BOX (SN)	CUT	480.00	400.00
1	REAR BOX BRACKET (SN)	TO REPAIR SEE LABOUR	180.00	-
			1,039.00	410.00
	<b><u>LABOUR</u></b>			
	TO PROVIDE TOWING SERVICE.		50.00	50.00
	TO CHECK WIRING AND RESET HEADLAMP FORCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	380.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF MAIN STAND AND REAR BOX BRACKET.		480.00	300.00
			990.00	350.00
	<b>GRAND TOTAL</b>		<b>7,244.50</b>	<b>2,732.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,150.00</b>

Report Ref No. CS/UI021003710/Uff3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.