



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 2435L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	1,508.90	1,508.90
1	REAR BUMPER SIDE BRACKET LOWER O/S	CRACKED	27.00	27.00
1	REAR BUMPER CHROME MOULDING	BENT	216.40	168.21
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	77.90	-
1	REAR PARKING SENSOR CENTRE RH	SERVICEABLE	258.10	-
1	REAR END PANEL	NOT NECESSARY	1,336.80	-
	LESS 10% DISCOUNT		-342.51	-170.41
			3,082.59	1,533.70
	<u>LABOUR</u>			
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED PARTS.		680.00	200.00
	TO SAND DOWN,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PARTS.		480.00	300.00
	TO CHECK ALL WIRING.	NOT NECESSARY	50.00	-
	TO DISMANTLE & REINSTALL PARKING SENSOR.		120.00	40.00
			1,330.00	540.00
GRAND TOTAL			4,412.59	2,073.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CS/AGI21003714/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.