

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	R	Ref:	CS3/ASM21003717/R1tf3e2	
	8 SHENTON WAY TOWERSINGAPOR	_	D	ate:	05/04/2021	
	ATTN : TAN JUN H	IONG	C	ode:	ASM	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 7257U	Veh. Inspected		FY 4144P	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S1M035LB	Excess (\$)		0.00	
	Assign From	TAN JUN HONG	Assign Date		22/03/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	KAWASAKI KRR ZX150 M	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2004	
	Chassis No.	KR150KA60955	Colour		BLUE	
	Odometer	31604 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	70/90-17	MAXXIS		3 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80/90-17	MAXXIS		3 mm	
	L/H Rear Tyre				mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5.	General Information					
	Accident Date	15/03/2021	Inspect Date / Ti	me	23/03/2021 ( 03:49 PM )	
	Survey held at Blk 1005 Bukit Merah Lane 2 #01-18					
	Repairer	Repairer FRIENDSHIP MOTOR CO				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM21003717/R1tf3e2

Inspected By

**Automotive Assessor** 

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

PEOP Auto Occupitant OAE Liverand America

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$