

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

22/03/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP INC.
Denise

Accident date: 22/03/2021

Estimated repair cost for vehicle no: SMS2644A HONDA ACCORD 1.5 VTEC TURBO

CHASSIS: MRHCV1650KP000022

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>cracked</i>		\$1,224.65 <i>957.20</i>
2	2	Rear Boot Lid Hinge <i>new</i>	\$86.40	\$172.80 <i>x</i>
3	1	Rear Boot Lid Emblem Logo <i>new</i>		\$39.00 <i>✓</i>
4	1	Rear Boot Lid Center Garnish <i>new</i>		\$324.60 <i>x</i>
5	1	Rear Boot Lid Accord Logo <i>new</i>		\$45.60 <i>✓</i>
6	1	Rear Boot Lid Number Plate		\$50.00 <i>+</i>
7	2	Rear Boot Lid Side Reflector Top <i>new</i>	\$264.25	\$528.50 <i>+</i>
8	2	Rear Boot Lid Side Reflector Lower	\$221.45	\$442.90 <i>+</i>
9	1	Rear Boot Lid Inner Lock <i>damaged</i>		\$121.20 <i>✓</i>
10	1	Rear Boot Lid Inner Rubber		\$25.60 <i>+</i>
11	1	Rear Boot Lid Inner Trim Board		\$124.50 <i>+</i>
12	8	Rear Boot Lid Inner Trim Board Clip	\$6.50	\$52.00 <i>+</i>
13	2	Rear Tail Lamp <i>cracked</i>	\$880.90	\$1,761.80 <i>1120</i>
14	4	Rear Tail Lamp Clip <i>new</i>	\$6.50	\$26.00 <i>✓</i>
15	1	Rear Bumper <i>deformed</i>		\$1,091.30 <i>631.20</i>
16	1	Rear Bumper Lower <i>Moulding Deformed</i>		\$178.00 <i>✓</i>
17	1	Rear Bumper Lower Center Garnish <i>Deformed</i>		\$60.00 <i>✓</i>
18	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 <i>30</i>
19	2	Rear Bumper Side Retainer <i>new</i>	\$21.10	\$42.20 <i>✓</i>
20	2	Rear Bumper Side Reflector <i>HA cracked</i>	\$85.50	\$171.00 <i>85.50</i>
21	1	Rear Bumper Reinforcement <i>Dented</i>		\$783.20 <i>606.20</i>
22	4	Rear Bumper Reverse Sensor <i>2 pieces damaged</i>	\$291.70	\$1,166.80 <i>420</i>
23	4	Rear Bumper Reverse Sensor Holder Bracket <i>new</i>	\$35.00	\$140.00 <i>✓</i>
24	4	Rear Bumper Reverse Sensor Rubber Seal <i>new</i>	\$18.00	\$72.00 <i>✓</i>
25	1	Rear End Panel <i>Dented</i>		\$595.80 <i>✓</i>
26	1	Rear End Panel Top Garnish <i>Deformed</i>		\$84.00 <i>✓</i>
27	1	Rear Spare Tyre Panel <i>Repair</i>		\$619.60 <i>+</i>
28	1	Rear Spare Tyre Panel Top Cover <i>Deformed</i>		\$210.00 <i>✓</i>

29	1	Rear Spare Tyre Panel Tool Foam	behind	\$103.00	✓
30	2	Rear Exhaust Chrome	Lit wt	\$419.30	\$838.60 185
31	1	Rear Exhaust	Not m	\$1,445.90	X
32	2	Rear Exhaust Mounting	not m	\$24.00	\$48.00 X

5611.90
4489.52

Subtotal :- \$12,640.55

Labour charges

To remove & refit reverse sensor	\$120.00 60
To remove & refit cushion & trim board	\$280.00 60
To remove & refit rear & center exhaust	\$380.00 X
To check wiring	\$100.00 30
Tuff kote	\$150.00 60
Panel beating	\$1,200.00 800
Spray painting	\$1,200.00 800

Subtotal :- \$3,430.00

Total:- \$16,070.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 6259.52

L/s: SK

05 Days.

SK