

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Re	ef:	CS3/ASM21003723/R1tf3e2
	8 SHENTON WAY TOWERSINGAPOR	Da	ate:	07/04/2021	
	ATTN: DANIEL PA	Υ	Co	ode:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YN 5847X	Veh. Inspected		XD 5903G
	Policy No.	VFX/P2422168	Coverage (\$)		0.00
	Claim No.	S1M035X5	Excess (\$)		0.00
	Assign From	DANIEL PAY	Assign Date		23/03/2021
2.	Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FP51JDR4RDEA	c.c		12882
	Engine No.	HIDDEN	Year of Reg.		2012
	Chassis No.	FP51JDA00907	Colour		BLUE
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	295/80 R22.5	O'GREEN		8 mm
	L/H Front Tyre	295/80 R22.5	O'GREEN		8 mm
	R/H Rear Tyre	295/80 R22.5 (D)	O'GREEN		8/8 mm
	L/H Rear Tyre	295/80 R22.5 (D)	O'GREEN		8/8 mm
4.	Description of Damages				
	THE VEHICLE SUS	EVEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5.	General Information				
	Accident Date	19/03/2021	Inspect Date / Tim	ne	23/03/2021 (12:19 PM)
	Survey held at	YEE KEONG MOTOR ENGINEE	RING		
	NO: 14 PENJURU ROAD SINGAPORE 609125				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$20,000-\$25,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 17 Working Days				

Report Ref No. CS3/ASM21003723/R1tf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser