



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 1209R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,650.00	1,042.20
1	FRONT BUMPER "BMW" LOGO	NECESSARY	98.00	71.95
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	115.00	-
1	FOG LAMP GARNISH RH	NOT NECESSARY	125.00	-
1	HEADLAMP RH	CRACKED	2,710.00	2,130.35
1	HEADLAMP LOWER BRACKET RH	NOT NECESSARY	95.00	-
1	HEADLAMP SPRAY NOZZLE RH	NOT NECESSARY	155.95	-
1	HEADLAMP SPRAY NOZZLE COVER RH	CUT	75.00	55.00
1	HEADLAMP SPRAY NOZZLE BRACKET RH	NOT NECESSARY	69.50	-
1	HEADLAMP HOSELINE CLEANING SYSTEM	NOT NECESSARY	115.00	-
	LESS 10% DISCOUNT		-520.85	-329.95
			4,687.60	2,969.55
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	65.00	40.00
2	HEADLAMP CLIP RH @\$8.00 (SN)	NOT NECESSARY	16.00	-
			81.00	40.00
<u>LABOUR</u>				
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		120.00	20.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.		400.00	150.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		400.00	200.00
			920.00	370.00
GRAND TOTAL			5,688.60	3,379.55



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00
---	--	--	-----------------

Report Ref No. CS/SMO21003726/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.