LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CS/AIG21003733/EVF3E2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 **Date:** 15/04/2021

REFERENCE

Insured/Claimant: CHIN CHE CHUNG Policy No: 1700090614

Date of Loss: 13/03/2021 Nature of Claim: OD Claim No: 3426835712SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV1391G

 Make & Model:
 KIA NIRO HYBRID, 1.6 (A)
 Engine No:
 G4LEHS245821

 Reg. Date:
 22/12/2017 (Man. Year: 2017)
 Chassis No:
 KNACC81CVJ5115249

Colour: Grey Odometer: 51631 km

Engine Capacity: 1580 cc
Market Value/New Car Price: \$\$75,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm
Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		439.20	426.40	12.80	2.91
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,290.00	1,250.00	1,040.00	45.41
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,729.20	1,676.40	1,052.80	38.58
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	2,129.20	1,076.40	1,052.80	49.45
	+ GST 7.00/7.00% (S\$)	149.04	75.35	73.69	49.44
	Nett Amount (S\$)	2,278.24	1,151.75	1,126.49	49.45

INSPECTION

Date of Assignment: 23/03/2021

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)

Date Inspected: 23/03/2021 Inspected At: 209 Pandan Gardens

Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*PIECE-FRT BUMPER GUARD LWR, RH	Not Necessary	16.00 FL	*-FL
3	1		*GARNISH ASSY-FNDR SIDE, RH	Cut	123.00 FL	*123.00 FL
4	1		*PANEL-FENDER, RH	Dented	385.00 FL	*385.00 FL
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	544.00	528.00
			- List Item Discount on L Ite	ms 20.00/20.00% (S\$)	104.80	101.60
				Total Parts (S\$)	439.20	426.40
			Report was unsubmitted during t	nis print-out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	RENEW FRT FENDER RH. REPAIR FRT DOOR RH	New	1,400.00	400.00
2	RESPRAY FRT FENDER RH & FRT DOOR RH	New	700.00	700.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO USING HI-SCAN PRO TEST	TEST New	120.00	120.00
5	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	0.00
	Gros	ss Labour Cost (S\$)	2,290.00	1,250.00
	Report was unsubmitted d	uring this print-out.		

< END OF ESTIMATES >