

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003737/URA3Q2
Date: 12/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993664
Claimant Vehicle No :	GBG2218R	Insured Vehicle No :	GBJ380B
Date of Loss:	17/03/2021	Nature of Claim:	TP
		Claim No:	3711022382SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG2218R		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2707380
Reg. Date:	29/06/2017 (Man. Year: 2017)	Chassis No:	JTFAT35Y20K208176
Colour:	Silver	Odometer:	114636 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,373.57	1,956.50	1,417.07	42.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,625.00	1,055.00	570.00	35.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,998.57	3,011.50	1,987.07	39.75
Approved Total (Overridden) (S\$)		2,400.00		

(S\$)	4,998.57	2,400.00	2,598.57	51.99
+ GST 7.00/7.00% (S\$)	349.90	168.00	181.90	51.99
Nett Amount (S\$)	5,348.47	2,568.00	2,780.47	51.99
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,875.45		

INSPECTION

Date of Assignment: 23/03/2021

Date Inspected: 23/03/2021

Estimated Period of Repair: 3.0 days

 Inspected At: NPH Auto Service (HQ)
 Blk 9005 Tampines Steet 93, #01-246/254
 Singapore 528839
Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP ASSY RH	Cracked	1,145.80 FL	*1,145.80 FL
2	1		*FRONT BUMPER	Torn	529.70 FL	*529.70 FL
3	1		*FRONT BUMPER BRACKET	Bent	225.10 FL	*225.10 FL
4	1		*FRONT STEPBOARD FIBRE	Cracked	400.00 FL	*366.10 FL
5	1		*FRONT DOOR RH	Repair	1,600.00 FL	*- FL
6	1		*FRONT DOOR W/STRIP RUBBER	Not Necessary	195.00 FL	*- FL
7	1		*FRONT SIDE PANEL RH	Cracked	212.50 FL	*212.50 FL
8	1		*FRONT BUMPER FOG LAMP GRILLE RH	Missing	70.00 FL	*62.80 FL
9	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*20.00 FS
10	1		*FRONT DOOR BODY LETTERING	Necessary	45.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,468.10	2,592.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,094.53	635.50
Total Parts (\$)	3,373.57	1,956.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & INSTALL F/DOOR ,F/HEADLAMP ,F/BUMPER ,SIDE PANEL ,F/HEADLAMP ,F/BUMPER ,KNOCK DOOR PILLAR AND RESTRAIGHTEN BODY	New	750.00	480.00
2	SPRAY PAINTING	New	850.00	550.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
Gross Labour Cost (S\$)			1,625.00	1,055.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >