

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21003744/ATD3N2**Date:** 20/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00113352001

**Claimant Vehicle
No :** SJP5243E**Insured Vehicle
No :** SKL254R

Date of Loss: 15/03/2021

Nature of Claim: TP

Claim
No: SNM21D201487/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJP5243E**

Make & Model: HYUNDAI AVANTE, 1.6 HD (A)

Engine No: G4FC9U623142

Reg. Date: 27/03/2009 (Man. Year: 2009)

Chassis No: KMHU41BR9U719321

Colour: Maroon

Odometer: 173951 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17

Rear Tyre Size: 215/45R17

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,024.32	5,650.64	14,373.68	71.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,650.00	2,350.00	5,300.00	69.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,674.32	8,000.64	19,673.68	71.09
Approved Total (Overridden) (\$\$)		6,400.00		
Nett Amount (\$\$)	27,674.32	6,400.00	21,274.32	76.87

INSPECTION

Date of Assignment: 22/03/2021

Date Inspected: 22/03/2021 Inspected At:

8 KAKI BUKIT AVE 4

#01-49 PREMIER

REPAIRER: 1ST AUTO PRO PTE LTD

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2021)
Parts:	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP5243E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,021.20 FL	*- FL
2	2		*BONNET HINGE LH/RH	Not Necessary	216.00 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	215.00 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	198.70 FL	*- FL
5	1		*BONNET LOCK COVER	Not Necessary	154.00 FL	*- FL
6	1		*BONNET WEATHERSTRIP	Not Necessary	131.90 FL	*- FL
7	1		*FRONT BUMPER	Deformed	598.00 FL	*478.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Cracked	267.50 FL	*105.00 FL
9	2		*FRONT BUMPER FOGLAMP COVER LH/RH	Not Necessary	492.00 FL	*- FL
10	2		*FRONT BUMPER SIDE RETAINER LH/RH	Necessary	220.00 FL	*75.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	589.00 FL	*254.00 FL
12	1		*FRONT BUMPER SPONGE	Cracked	316.40 FL	*118.00 FL
13	2		*FRONT FENDER INNER COWLING LH/RH	Not Necessary	390.80 FL	*- FL
14	2		*HEAD LAMP LH/RH	Cracked	1,856.00 FL	*1,164.00 FL
15	2		*HEAD LAMP LOWER BRACKET LH/RH	Not Necessary	338.80 FL	*- FL
16	1		*FRONT SUPPORT PANEL	Not Necessary	865.00 FL	*- FL
17	1		*FRONT SUPPORT PANEL UNDER COVER	Not Necessary	256.00 FL	*- FL
18	1		*REAR BUMPER	Deformed	644.00 FL	*495.00 FL
19	2		*REAR BUMPER RETAINER LH/RH	Necessary	334.00 FL	*70.00 FL
20	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	340.00 FL	*- FL
21	1		*REAR BUMPER REINFORCEMENT	Distorted	454.00 FL	*282.00 FL
22	1		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	O/s Dented	312.00 FL	*125.00 FL
23	1		*REAR BUMPER SPONGE	Cracked	310.00 FL	*119.00 FL
24	1		*REAR WINDSCREEN MOULDING	Not Necessary	218.00 FL	*- FL
25	1		*BOOTLID	Dented	985.90 FL	*985.90 FL
26	1		*BOOTLID EMBLEM AVANTE	Necessary	156.00 FL	*52.00 FL
27	1		*BOOTLID EMBLEM S	Necessary	117.00 FL	*48.00 FL
28	1		*BOOTLID REFLECTOR LH/RH	O/s Cracked	980.00 FL	*241.00 FL
29	1		*BOOTLID NUMBER PLATE LAMP	Not Necessary	124.20 FL	*- FL
30	2		*BOOTLID HINGE LH/RH	Not Necessary	528.00 FL	*- FL
31	2		*BOOTLID STOPPER LH/RH	Not Necessary	272.40 FL	*- FL
32	1		*BOOTLID INNER TRIM	Not Necessary	384.00 FL	*- FL
33	1		*BOOTLID LOGO	Necessary	137.40 FL	*39.00 FL
34	1		*BOOTLID TOP LOCK	Damaged	248.00 FL	*158.00 FL
35	1		*BOOTLID LOWER LOCK	Not Necessary	142.70 FL	*- FL
36	1		*BOOTLID WEATHERSTRIP	Cut	321.00 FL	*165.00 FL
37	1		*TAILLAMP LH/RH	O/s Cracked	1,616.00 FL	*287.00 FL
38	1		*TAILLAMP PANEL LH/RH	O/s Dented	1,156.00 FL	*175.00 FL
39	2		*REAR FENDER INNER COWLING LH/RH	Not Necessary	394.80 FL	*- FL
40	1		*REAR FENDER INNER TRIM LH/RH	O/s Torn	978.00 FL	*245.00 FL
41	1		*REAR END PANEL	Dented	780.00 FL	*485.00 FL
42	1		*REAR END PANEL TOP GARNISH	Cracked	245.00 FL	*86.00 FL
43	1		*REAR FLOOR PANEL	Repair	986.90 FL	*- FL
44	1		*REAR FLOOR PANEL TOP BOARD	Torn	286.40 FL	*286.40 FL
45	1		*REAR FLOOR PANEL TOOLS BOX	Not Necessary	287.40 FL	*- FL
46	1		*REAR EXHAUST PIPE	Repair	965.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT NUMBER PLATE	Dented	100.00 FS	*50.00 FS
48	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
49	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
50	1		*BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
51	1		*FRONT FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
52	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
53	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
54	1		*REAR WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
55	1		*BOOT LID SEALANT	Not Necessary	80.00 FS	*- FS
56	1		*BOOT LID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
57	1		*BOOTLID OUTER MOULDING CLIP	Not Necessary	50.00 FS	*- FS
58	1		*TAIL LAMP CLIP	Necessary	50.00 FS	*10.00 FS
59	1		*TAIL LAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
60	1		*REAR FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
61	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
62	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
63	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
64	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	250.00 FS	*- FS
65	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,590.40	6,958.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,566.08	1,307.66
Total Parts (\$\$)	20,024.32	5,650.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT AND TRANSFER FRONT BUMPER + REAR BOOT COMPONENT	New	300.00	0.00
2	TO REMOVE AND REFIT ELECTRICAL WIRING,REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING-FRONT + REAR	New	300.00	60.00
3	TO RMEOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR-FRONT + REAR	New	300.00	80.00
4	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	50.00
5	TO REMOVE AND REFIT REAR WINDSCREEN	New	200.00	0.00
6	TO REMOVE AND REFIT,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTING	New	350.00	0.00
7	TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	New	100.00	60.00
8	TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	New	3,000.00	1,000.00
9	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	New	3,000.00	1,100.00
Gross Labour Cost (\$)			7,650.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >