

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21003753/QGS3Q2
Date: 03/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SHD6093B	Insured Vehicle No :	GBJ6273M
Date of Loss:	17/03/2021	Nature of Claim:	TP
		Claim No:	2876011886SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6093B	Engine No:	2ZR6609120
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKN36U405768492
Reg. Date:	27/07/2016 (Man. Year: 2015)	Odometer:	371105 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Touring 6 mm	Rear Left Side:	Touring 6 mm
Front Right Side:	Touring 6 mm	Rear Right Side:	Touring 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,687.70	1,747.06	6,940.64	79.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,692.00	1,050.00	1,642.00	61.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,379.70	2,797.06	8,582.64	75.42
Approved Total (Overridden) (S\$)		2,450.00		

Nett Amount (S\$)	11,379.70	2,450.00	8,929.70	78.47
+ Loss of Use (5.5 x S\$50.00/day) (S\$)		275.00		
+ Car Rental (5.5 x S\$107.00/day) (S\$)		588.50		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,320.50		

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 19/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Crumpled	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	21.00 F	*15.75 F
3	1		*TAILGATE ASY (DISC 25%)	Dented	1,007.90 F	*755.93 F
4	1		*TAILGATE DOOR GLASS MOULDING RH (DISC 25%)	Necessary	29.40 F	*22.05 F
5	1		*TAILGATE DOOR GLASS MOULDING ,LH (DISC 25%)	Necessary	29.40 F	*22.05 F
6	1		*MOULDING BACK WINDOW LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
7	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F
8	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
9	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
10	3		*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
11	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
12	1		*ARM SUB-ASSY ,RR BUMPER RH	Serviceable	139.60 F	*- F
13	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
14	1		*ANTENNA ,ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
15	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
16	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
17	1		*BUMPER SEAL ,RR LH	Serviceable	88.90 F	*- F
18	1		*BUMPER SEAL ,RR RH	Serviceable	65.70 F	*- F
19	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
20	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
21	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
22	1		*UNDER COVER SUB-ASSY ,RR FLOOR	Serviceable	514.50 F	*- F
23	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
24	1		*END PANEL	Serviceable	602.10 F	*- F
25	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
26	1		*TAILGATE DOOR GLASS	Serviceable	1,090.90 F	*- F
27	1		*TAILGATE LOWER WINDOW GLASS	Serviceable	721.30 F	*- F
28	1		*SPOILER REAR	Serviceable	953.70 F	*- F
29	1		*TAIL LAMP RH	Serviceable	557.80 F	*- F
30	1		*TAIL LAMP LH	Serviceable	548.40 F	*- F

F=Franchise part.

Total Parts (S\$) 8,687.70 1,747.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	1,296.00	400.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
4	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	50.00
5	TO REMOVE AND REFIX TAILGATE GLASS	New	120.00	100.00
6	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	60.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
9	TO WASH AND VACUUM	New	60.00	0.00
			Gross Labour Cost (\$\$)	2,692.00
				1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >