

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21003756/KQF3N2**Date:** 18/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900152507
Claimant Vehicle No :	SFF2345P	Insured Vehicle No :	SFZ1008P
Date of Loss:	19/03/2021	Nature of Claim:	TP
		Claim No:	6523953446SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFF2345P	Engine No:	27294630648716
Make & Model:	MERCEDES-BENZ S300L, 3.0 (A)	Chassis No:	WDD2211542A147020
Reg. Date:	24/09/2007 (Man. Year: 2007)	Odometer:	106913 km
Colour:	Metallic Black		
Engine Capacity:	2997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R17	Rear Tyre Size:	235/55R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,902.90	3,944.00	13,958.90	77.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	780.00	2,750.00	77.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,432.90	4,724.00	16,708.90	77.96
Approved Total (Overridden) (S\$)		3,750.00		
Nett Amount (S\$)	21,432.90	3,750.00	17,682.90	82.50

INSPECTION

Date of Assignment:	22/03/2021	S Three Automotive Recovery Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C Singapore 575643
Date Inspected:	23/03/2021 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	3,100.00 FL	*- FL
2	1		*REAR BOOTLID S300 EMBLEM	Not Necessary	75.00 FL	*- FL
3	1		*REAR BOOTLID LOGO	Not Necessary	78.00 FL	*- FL
4	1		*REAR BOOTLID 7G TRONIC EMBLEM	Not Necessary	122.00 FL	*- FL
5	1		*REAR BOOTLID INNER LOCK MECHANISM	Repair	780.00 FL	*- FL
6	1		*REAR BOOTLID CATCH	Repair	232.00 FL	*- FL
7	1		*REAR BOOTLID WEATHERSTRIP	Serviceable	228.00 FL	*- FL
8	1		*REAR BOOTLID INNER TRIM	Serviceable	620.00 FL	*- FL
9	1		*REAR BOOTLID CHROME MOULDING	Serviceable	580.00 FL	*- FL
10	1		*REAR BOOTLID SIDE GARNISH INNER RH	Serviceable	176.00 FL	*- FL
11	1		*REAR BUMPER	Bent	2,100.00 FL	*1,840.00 FL
12	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	148.00 FL	*- FL
13	1		*REAR BUMPER SIDE RETAINER RH	Cracked	148.00 FL	*120.00 FL
14	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	986.00 FL	*650.00 FL
15	1		*REAR BUMPER REINFORCEMENT BRACKET	Repair	376.00 FL	*- FL
16	1		*REAR BUMPER TOW COVER	Serviceable	48.00 FL	*- FL
17	1		*REAR BUMPER INNER PLASTIC BEAM	Serviceable	832.00 FL	*- FL
18	1		*TAILLAMP RH	Cracked	2,140.00 FL	*650.00 FL
19	1		*TAILLAMP BRACKET RH	Serviceable	680.00 FL	*- FL
20	1		*TAILLAMP MOULDING RH	Serviceable	320.00 FL	*- FL
21	1		*REAR END PANEL	Repair	1,039.00 FL	*- FL
22	1		*REAR END PANEL TOP GARNISH	Serviceable	265.00 FL	*- FL
23	1		*REAR EXHAUST SHIELD	Dented	283.00 FL	*235.00 FL
24	1		*REAR SPARE TYRE FIBRE PANEL	Serviceable	1,080.00 FL	*- FL
25	1		*KEYLESS SENSOR	Serviceable	380.00 FL	*- FL
26	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
27	1		*REVERSE SENSOR WITH HOLDERS	Shorted	1,200.00 FS	*260.00 FS
28	1		*REVERSE SENSOR WIRE HARNESS	Cut	790.00 FS	*250.00 FS
29	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	280.00 FS	*- FS
31	1		*REAR BOOTLID INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
32	1		*REAR BUMPER LOWER BRACKET LH	Cracked	90.00 FL	*90.00 FL
33	1		*REAR BUMPER LOWER BRACKET RH	Cracked	90.00 FL	*90.00 FL
34	1		*TAILLAMP SIDE GARNISH COVER RH	Distorted	85.00 FL	*85.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,611.00	4,320.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,708.10	376.00
Total Parts (\$\$)	17,902.90	3,944.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	1,200.00	250.00
2	SPRAY PAINTING ON ACCIDENT AREA	New	1,200.00	480.00
3	CHECK & REPAIR WIRING SYSTEM	New	150.00	20.00
4	R&R BOOTLID COMPARTMENT	New	150.00	0.00
5	RESET BOOTLID LOCK MECHANISM	New	150.00	0.00
6	R&R EXHAUST HEATSHIELD SYSTEM	New	150.00	30.00
7	RESPRAY TUFF KOTE ON ACCIDENT AREA	New	150.00	0.00
8	R&R REVERSE SENSOR & RESETTING OF SYSTEM	New	380.00	0.00
Gross Labour Cost (\$)			3,530.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >