

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21003757/QTF3E2

Date: 08/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700010916
Claimant Vehicle No :	SLN9253L	Insured Vehicle No :	GBG602C
Date of Loss:	19/03/2021	Nature of Claim:	TP
		Claim No:	3079430854SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN9253L	Engine No:	G4FGHU116362
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMHU459386
Reg. Date:	23/05/2017 (Man. Year: 2017)	Odometer:	73546 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/03/2021		
Date Inspected:	23/03/2021	Inspected At:	Assure Auto (HQ) B14 AMK BLK B Singapore 569116
Estimated Period of Repair:	12.0 days		

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Dented	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Crumpled	0.00 F	*- F
3	1		*FRT NUMBER PLATE GARNISH	Crumpled	0.00 F	*- F
4	1		*FRT BUMPER	Crumpled	0.00 F	*- F
5	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
8	1		*FRT BUMPER BEAM	Bent	0.00 F	*- F
9	1		*FRT BUMPER SPONGE	Crumpled	0.00 F	*- F
10	1		*FRT BUMPER GRILLE	Crumpled	0.00 F	*- F
11	1		*FRT LH BUMPER FOG LAMP COVER	Crumpled	0.00 F	*- F
12	1		*FRT LH BUMPER FOG LAMP	Crumpled	0.00 F	*- F
13	1		*FRT GRILLE	Crumpled	0.00 F	*- F
14	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
15	1		*FRT GRILLE CHROME MOULDING	Crumpled	0.00 F	*- F
16	1		*FRT SUPPORT PANEL	Cracked	0.00 F	*- F
17	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Crumpled	0.00 F	*- F
18	1		*FRT LH HEADLAMP ASSY	Crumpled	0.00 F	*- F
19	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
20	1		*BONNET	Dented	0.00 F	*- F
21	1		*BONNET LOCK	Jammed	0.00 F	*- F
22	2		*BONNET HINGE	Bent	0.00 F	*- F
23	1		*BONNET RUBBER	Broken	0.00 F	*- F
24	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
25	1		*RADIATOR	Bent	0.00 F	*- F
26	1		*RADIATOR COWLING	Cracked	0.00 F	*- F
27	1		*AIR CLEANER ASSY	Cracked	0.00 F	*- F
28	1		*ENGINE UNDER COVER	Crumpled	0.00 F	*- F
29	1		*FRT LH FENDER	Crumpled	0.00 F	*- F
30	1		*DASHBOARD ASSY	Broken	0.00 F	*- F
31	1		*STEERING WHEEL AIRBAG	Broken	0.00 F	*- F
32	1		*STEERING WHEEL AIRBAG SENSOR	Necessary	0.00 F	*- F
33	1		*DASHBOARD AIRBAG	Broken	0.00 F	*- F
34	1		*DASHBOARD AIRBAG SENSOR	Necessary	0.00 F	*- F
35	1		*AIRBAG CONTROL UNIT	Necessary	0.00 F	*- F
36	1		*FRT DRIVER SEAT	Jammed	0.00 F	*- F
37	1		*FRT PASSENGER SEAL	Jammed	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
--------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >