

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21003763/DTF3E2

Date: 28/01/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001621308
Claimant Vehicle No :	SHD7283M	Insured Vehicle No :	SLF9162H
Date of Loss:	22/03/2021	Nature of Claim:	TP
		Claim No:	254986

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD7283M	Engine No:	G4LEJU132615
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU121948
Reg. Date:	04/12/2018 (Man. Year: 2018)	Odometer:	188144 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,620.32	5,717.52	8,902.80	60.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,080.00	2,020.00	49.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,720.32	7,797.52	10,922.80	58.35
+ GST 7.00/7.00% (S\$)	1,310.42	545.83	764.59	58.35
Nett Amount (S\$)	20,030.74	8,343.35	11,687.39	58.35

INSPECTION

Date of Assignment:	24/03/2021	
Date Inspected:	24/03/2021	Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jan 2022)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD7283M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID RUBBER	Necessary	187.40 FL	*187.40 FL
3	1		*BOOT LID LOCK UPPER	Serviceable	224.00 FL	*- FL
4	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
5	1		*EMBLEM-HYBRID	Necessary	24.30 FL	*24.30 FL
6	1		*EMBLEM-IONIQ	Necessary	31.30 FL	*31.30 FL
7	1		*BOOT LID TRIMBOARD	Not Necessary	259.70 FL	*- FL
8	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
9	1		*BOOT LID TRIMBOARD, CENTRE	Not Necessary	159.60 FL	*- FL
10	1		*BOOT LID TRIMBOARD SIDE (LH/RH)	Not Necessary	92.50 FL	*- FL
11	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
12	1		*BOOT LID GLASS UPPER MOULDING	Necessary	186.30 FL	*186.30 FL
13	1		*BOOT LID GLASS LOWER MOULDING	Not Necessary	145.20 FL	*- FL
14	1		*REAR BUMPER	Dented / Broken	459.40 FL	*459.40 FL
15	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
16	1		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	N/S Cracked/O/S Not Necessary	376.20 FL	*188.10 FL
17	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	*451.25 FL
18	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Mtg Broken	47.50 FL	*47.50 FL
19	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
20	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Serviceable	171.60 FL	*- FL
21	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
22	1		*REAR BUMPER UNDER CENTRE	Serviceable	123.85 FL	*- FL
23	2		*REAR BUMPER SIDE UNDER (LH/RH)	Not Necessary	246.20 FL	*- FL
24	1		*REAR BUMPER REAR HOOK	Not Necessary	94.60 FL	*- FL
25	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	165.80 FL	*- FL
26	1		*REAR BUMPER TOWING COVER	Serviceable	98.80 FL	*- FL
27	1		*REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	Socket Broken	328.60 FL	*328.60 FL
28	2		*LICENCE LAMP (LH/RH)	Not Necessary	170.60 FL	*- FL
29	1		*LICENCE LAMP WIRE	Not Necessary	135.80 FL	*- FL
30	1		*TAIL LAMP QUARTER PANEL (LH)	Not Necessary	208.90 FL	*- FL
31	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
32	1		*REAR PANEL GARNISH	Mtg Deformed	346.80 FL	*346.80 FL
33	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
34	1		*SPARE WHEEL LOCK NUT	Not Necessary	89.50 FL	*- FL
35	1		*SPARE TYRE PANEL	Dented	892.50 FL	*892.50 FL
36	1		*REAR TRAY TOOLS BOX RH	Not Necessary	675.30 FL	*- FL
37	1		*REAR TRAY TOOLS BOX LH	Not Necessary	693.20 FL	*- FL
38	1		*REAR TRAY LUGGS CENTER	Not Necessary	354.20 FL	*- FL
39	1		*REAR FENDER (LH)	Repair	1,768.30 FL	*- FL
40	1		*REAR FENDER SHIELD REAR PIECE (RH)	Not Necessary	173.60 FL	*- FL
41	1		*REAR FENDER SHIELD FRT PIECE (LH)	Not Necessary	165.50 FL	*- FL
42	1		*REAR FENDER CORNER INNER UPPER GARNISH (LH)	Not Necessary	486.70 FL	*- FL
43	1		*REAR FENDER AIR-DUCT (LH)	Not Necessary	87.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR FENDER TRIM BOARD (LH)	Not Necessary	788.75 FL	*- FL
45	1		*WIRING HARNESS BWS EXT	Not Necessary	988.90 FL	*- FL
46	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	35.00 FS	*35.00 FS
47	1		*BOOT LID COMFORT CABLINK TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
48	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 FS	*92.00 FS
49	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
50	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
51	1		*SPARE TYRE PANEL SILICON	Necessary	250.00 FS	*50.00 FS
52	1		*ASSY BSD BLIND SPOT RADAR (LH)	Not Necessary	1,625.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,116.15	7,037.65
- List Item Discount on L Items 20.00/20.00% (\$)	3,495.83	1,320.13
Total Parts (\$)	14,620.32	5,717.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING CHARGE	New	1,200.00	800.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE / REFIX FUEL TANK	New	80.00	0.00
9	REMOVE / REFIX EXHAUST PIPE	New	80.00	60.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
11	REMOVE / REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
Gross Labour Cost (\$\$)			4,100.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >