

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21003767/KGA3Q2**Date:** 02/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100448477
<b>Claimant Vehicle No :</b>	SLM2933J	<b>Insured Vehicle No :</b>	SKX513E
Date of Loss:	20/03/2021	Nature of Claim:	TP
		Claim No:	0823263427SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLM2933J</b>	Engine No:	1NZE939345
Make & Model:	TOYOTA AXIO, 1.5 X (A)	Chassis No:	NZE1617122157
Reg. Date:	27/03/2017 (Man. Year: 2015)	Odometer:	173513 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Tourador 4 mm	Rear Left Side:	Tourador 4 mm
Front Right Side:	Tourador 4 mm	Rear Right Side:	Tourador 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	996.66	906.58	90.08	9.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	1,050.00	290.00	21.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,336.66</b>	<b>1,956.58</b>	<b>380.08</b>	<b>16.27</b>
<b>+ GST 7.00/7.00% (S\$)</b>	163.57	136.96	26.61	16.27
<b>Nett Amount (S\$)</b>	<b>2,500.23</b>	<b>2,093.54</b>	<b>406.69</b>	<b>16.27</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		8.00		
<b>Nett Liability (S\$)</b>		<b>2,501.54</b>		

INSPECTION

Date of Assignment:	24/03/2021	
Date Inspected:	05/04/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	530.50 FL	*530.50 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Distorted	96.30 FL	*96.30 FL
3	1		*REAR BUMPER RH REFLECTOR	Serviceable	60.30 FL	*- FL
4	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*RH TAILLAMP	Cracked	560.98 FL	*560.98 FL
6	1		*RH TAILLAMP LOWER RETAINER	Serviceable	59.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

	<b>Sub Total (\$)</b>	<b>1,328.88</b>	<b>1,208.78</b>
- List Item Discount on L Items 25.00/25.00% (\$)		332.22	302.20
	<b>Total Parts (\$)</b>	<b>996.66</b>	<b>906.58</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS ,KNOCK & REPAIR REAR RH FENDER ,REAR PANEL & REALIGN THE SAME	New	600.00	450.00
2	PUTTY & RESPRAY ON REAR RH FENDER ,REAR PANEL ,REAR BUMPER	New	700.00	560.00
3	REMOVE & REFIX REVERSE SENSOR	New	40.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,340.00</b>	<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >