



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 4450X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DISTORTED	654.84	654.84
1	REAR BUMPER REFLECTOR (LH)	BROKEN	28.89	28.89
1	REAR BUMPER SIDE RETAINER (LH)	CRACKED	19.25	17.00
1	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	REAR BUMPER REINFORCEMENT	BENT	224.40	224.40
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	74.80	-
1	REAR BOOTLID	BENT / BUCKLED	712.62	712.62
1	REAR BOOT INNER LOCK	NOT NECESSARY	80.89	-
1	REAR BOOT KEY LOCK	NOT NECESSARY	99.36	-
1	REAR BOOT CATCH	NOT NECESSARY	65.30	-
2	REAR BOOT HINGE	N/S BENT	224.40	112.00
1	REAR BOOT RUBBER	TWISTED	130.90	130.90
1	MITSUBISHI LOGO	NECESSARY	56.10	56.10
1	"LANCER" EMBLEM	NECESSARY	90.45	58.00
1	CYCLE & CARRIAGE LOGO	NECESSARY	89.00	50.00
2	REAR BOOT LAMP	N/S CRACKED	542.30	260.00
1	REAR BOOT INNER TRIMBOARD	NOT NECESSARY	224.40	-
1	SET REAR BOOT INNER TRIMBOARD CLIP	NOT NECESSARY	50.00	-
2	TAILLAMP	N/S CRACKED	785.40	392.70
1	END PANEL	DENTED	504.90	496.00
1	END PANEL TOP GARNISH	TWISTED	187.00	187.00
1	REAR FENDER (LH)	DENTED / BUCKLED	897.60	845.00
1	REAR FENDER UNDER GARNISH (LH)	TORN	158.95	81.20
1	SET REAR FENDER UNDER GARNISH CLIP	NECESSARY	50.00	50.00
1	REAR FENDER INNER TRIM (LH)	TORN	220.00	220.00
1	AIR DUCT (LH)	TWISTED	46.75	46.75
1	SPARE TYRE TOP CARDBOARD	TORN	158.95	158.95
1	SPARE TYRE COMPARTMENT TOP COVER	REPEATED	185.60	-
1	SET REAR WINDSCREEN MOULDING	NECESSARY	121.55	86.00
1	REAR KEYLESS OPERATION BUZZER	NOT NECESSARY	285.60	-

Report Ref No. CS/AGI21003778/Uvf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-702.02	-491.84
			6,318.18	4,426.51
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	60.00	-
1	SET REAR REVERSE SENSOR (SN)	SHORTED	260.00	200.00
			450.00	290.00
	<b><u>LABOUR</u></b>			
	TOWING CHARGE (4-WHEEL).		150.00	120.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		80.00	20.00
	TO TRANSFER REAR BOOT COMPONENT PARTS TO NEW REAR BOOT.		150.00	60.00
	TO REMOVE & REINSTALL REAR WINDSCREEN.		150.00	120.00
	TO REMOVE,REPLACE,AND REINSTALL REAR REVERSE SENSORS.		80.00	50.00
	TO REMOVE & REINSTALL REAR BOOT TOP SPOILER.	NOT NECESSARY	80.00	-
	TO REMOVE & REINSTALL REVERSE CAMERA.	NOT NECESSARY	80.00	-
	TO APPLY ANTI-RUSTING COATING ON NEW AND AFFECTED AREAS.		200.00	80.00
	TO REMOVE & REINSTALL REAR INTERIOR TRIMS,GARNISHES ETC FOR NECESSARY REPAIR.		180.00	80.00
	TO REMOVE & REINSTALL PETROL TANK.		150.00	60.00
	LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING.		2,600.00	1,100.00
	TO PUTTY AND RESPRAY AFFECTED AREAS.		2,000.00	1,100.00
			5,900.00	2,790.00
<b>GRAND TOTAL</b>			<b>12,668.18</b>	<b>7,506.51</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,000.00</b>

Report Ref No. CS/AGI21003778/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.