

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21003783/AVF3N2
Date: 03/08/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004442000
Claimant Vehicle No : EU8810G **Insured Vehicle No :** SKH4802D
Date of Loss: 21/03/2021 Nature of Claim: TP Claim No: SNM21D201656/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EU8810G**
Make & Model: HONDA FIT, 1.3 G (A) Engine No: L13A4136545
Reg. Date: 15/01/2010 (Man. Year: 2009) Chassis No: GE61122942
Colour: Grey Odometer: 129797 km
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,443.28	2,963.12	2,480.16	45.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	2,100.00	1,930.00	47.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,473.28	5,063.12	4,410.16	46.55
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	9,473.28	3,500.00	5,973.28	63.05
+ GST 7.00/7.00% (S\$)	663.13	245.00	418.13	63.05
Nett Amount (S\$)	10,136.41	3,745.00	6,391.41	63.05

INSPECTION

Date of Assignment: 24/03/2021
Date Inspected: 12/04/2021 Inspected At: Smartone Auto Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2021)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/EU8810G/03/08/2021 09:51	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	849.90 FL	*849.90 FL
2	2		*TAILGATE WINDSCREEN MOULDING	Necessary	152.00 FL	*152.00 FL
3	1		*TAIL GATE INNER LOCK	Damaged	169.40 FL	*169.40 FL
4	1		*TAIL GATE LOCK CATCH	Not Necessary	25.00 FL	*- FL
5	1		*TAIL GATE WEATHER STRIP	Cut	134.50 FL	*134.50 FL
6	1		*TAIL GATE INNER TRIM	Cracked	372.20 FL	*285.00 FL
7	1		*REAR BUMPER	Deformed	490.00 FL	*490.00 FL
8	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	24.20 FL	*- FL
9	2		*REAR BUMPER BRACKET	Not Necessary	108.20 FL	*- FL
10	2		*REAR BUMPER SIDE RETAINER	Necessary	70.40 FL	*70.40 FL
11	2		*TAIL LAMP	Not Necessary	592.20 FL	*- FL
12	2		*TAIL LAMP LOWER BRACKET	Not Necessary	34.40 FL	*- FL
13	2		*REAR FENDER INNER COWLING	Not Necessary	156.20 FL	*- FL
14	2		*REAR FENDER INNER TRIM	Not Necessary	597.80 FL	*- FL
15	1		*REAR END PANEL	Dented	356.70 FL	*356.70 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	116.20 FL	*116.20 FL
17	1		*REAR FLOOR PANEL TOP BOARD	Deformed	185.60 FL	*185.60 FL
18	1		*REAR TOOLS COMPARTMENT	Cracked	294.20 FL	*294.20 FL
19	1		*REAR NUMBER PLATE (SPECIAL TYPE)	Not Necessary	180.00 FS	*- FS
20	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
21	1		*SET TAIL GATE OUTER MOULDING CLIP	Not Necessary	30.00 FS	*- FS
22	1		*SET TAIL GATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
23	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
24	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*60.00 FS
25	1		*TAIL GATE EMBLEM FIT (SPECIAL TYPE)	Necessary	150.00 FS	*60.00 FS
26	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
27	1		*SET REAR FENDER INNER COWLING	Not Necessary	50.00 FS	*- FS
28	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR FENDER INNER UPPER TRIM	Not Necessary	50.00 FS	*- FS
30	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
31	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
32	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
33	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,389.10	3,583.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	945.82	620.78
Total Parts (\$\$)	5,443.28	2,963.12

LKK Auto Consultants Pte Ltd/EU8810G/03/08/2021 09:51. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,200.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
8	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	New	80.00	50.00
9	REAR CHASSIS ALIGNMENT	New	250.00	0.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	TRANFER TAILGATE MECHANISM	New	80.00	80.00
12	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,030.00	2,100.00

LKK Auto Consultants Pte Ltd/EU8810G/03/08/2021 09:51. Not valid without Reference section.

< END OF ESTIMATES >