

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21003786/KTF3E2

**Date:** 29/07/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80465834QMY
<b>Claimant Vehicle No :</b>	SBR332Z	<b>Insured Vehicle No :</b>	SDR2278K
Date of Loss:	14/03/2021	Nature of Claim:	TP
		Claim No:	634600

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBR332Z</b>		
Make & Model:	VOLVO V90, 2.0 CROSS COUNTRY T5 MOMENTUM (A)	Engine No:	B4204T232142785
Reg. Date:	27/02/2018 (Man. Year: 2017)	Chassis No:	YV1PW10ADJ1041081
Colour:	Metallic Brown	Odometer:	74144 km
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/45Z R18	Rear Tyre Size:	245/45Z R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,577.20	3,396.50	2,180.70	39.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	800.00	1,200.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,577.20</b>	<b>4,196.50</b>	<b>3,380.70</b>	<b>44.62</b>
<b>+ GST 7.00/7.00% (S\$)</b>	530.40	293.76	236.64	44.62
<b>Nett Amount (S\$)</b>	<b>8,107.60</b>	<b>4,490.26</b>	<b>3,617.34</b>	<b>44.62</b>

### INSPECTION

Date of Assignment:	24/03/2021	
Date Inspected:	21/04/2021 Inspected At:	Tropical Success Auto Care (HQ) BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2 Singapore 569535
Estimated Period of Repair:	3.0 days	

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 Jul 2021)		
<b>Parts:</b>	N/A	VOLVO V90 2.0 CROSS COUNTRY T5 MOMENTUM (A) (Model not available in database)	
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SBR332Z)		
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.		

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT RUBBER	Serviceable	521.00 FL	*- FL
2	1		*REAR BUMPER	Cracked	2,982.00 FL	*2,451.00 FL
3	2		*REAR BUMPER PARKTRONIC SENSOR	Serviceable	724.00 FL	*- FL
4	1		*REAR BUMPER LIP	Dented / Distorted	483.00 FL	*483.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	1,448.00 FL	*801.00 FL
6	1		*REAR LICENSE SMART PLATE (NPA)	Not Necessary	0.00 FS	*- FS
7	1		*REAR LICENSE SMART PLATE CASING	Dented	35.00 FS	*35.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					<b>Sub Total (\$\$)</b>	<b>6,193.00 3,770.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>615.80 373.50</b>
					<b>Total Parts (\$\$)</b>	<b>5,577.20 3,396.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPARE PART ITEMS}	New	800.00	300.00
2	REMOVE AND REFIT REAR BOOT RUBBER, REAR BUMPER, REAR BUMPER PARKTRONIC SENSOR, REAR BUMPER LIP, REAR BUMPER REINFORCEMENT}	New	0.00	0.00
3	HEAT / PANEL / BEATING REAR BOOT, HEAT / WELD / BEATING / PULL / STRAIGHTEN / ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK}	New	0.00	0.00
4	DIAGNOSTIC TO RESET REAR BUMPER PARKTRONIC SENSOR FAULT ERROR BY HHT	New	150.00	60.00
5	UNDER COATING ON REAR DAMAGED PORTION	New	250.00	0.00
6	PUTTY / PRIMER APPLICATION, SPRAY PAINTING REAR BOOT, REAR BUMPER, REAR BUMPER PARKTRONIC SENSOR	New	800.00	440.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,000.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >