

Automobile Hub

SLZ 4428U.

TP AXA

Honda Vezel Hybrid.

Veron

RU31270247

Front Number Plate	Lt	30(SN) ✓
Front Number Plate Holder	Lt	30(SN) ✓
Front Bumper	Behind	821.40 ✓
Front Bumper Clips	Per	30(SN) ✓
Front Bumper Side Holder x 02	Per	$26.5 \times 2 = 53$ ✓
Front Bumper Reinforcement	Best	321 ✓
Front Bumper lower Grille	Assembled	162.90 ✓
Front Bumper lower Spoiler	Lt Per	386.20 X
Front Bumper Fog Lamp x 02	Lt Assembled	$327.2 \times 2 = 654.40$ 327.20
Front Bumper Fog Lamp Bracket x 02	Lt Assembled	$48 \times 2 = 96$ 48
Front Bumper Fog Lamp Covers	Lt Behind	$85 \times 2 = 170$ 85
Front Grille	Assembled	351.80 ✓
Front Grille Outer Moulding	Assembled	283.90 ✓
Front Grille Logo	Per	35.90 ✓
Front Grille Clips	Per	20(SN) ✓

3447.50

SLZ4428U.

Front Grille Inner Bracket ^{cauled} 69.40 ✓
Headlamp * 02 ^{LH cauled} 1784.50
Headlamp Lower Bracket x 02 ^{LH cauled} 39 x 2 = 78 39
Front Support Panel ^{Rep's} 676.60 +
Front Support Panel Top Cover ^{new} 190.30 +
Front Support Panel Top Cover clips. ^{new} 20 (SN) +
Front Inner Air Guide x 02 ^{LH cauled} 36 x 2 = 72 36
Bonnet ^{Dented} 992.30 ✓
Bonnet Lock ^{Dented} 95.10 ✓
Air Con Condenser. ^{new} 898 X
Front Wheel Arc Garnish x 02 ^{LH cauled} 153 x 2 = 306 153
Front Wheel Arc Garnish Clips. ^{new} 40 (SN)
20 (SN)

7006.70

SL74428U.

Rees Bumper	Del'd	880 ✓
Rees Bumper clips	Nu	30(SN) ✓
Rees Bumper Side Holder x02	Nu	$23.5 \times 2 = 47$ ✓
Rees Bumper Reflector x02	LH cubid	$141.1 \times 2 = 282.20$ ✓ 141.10.
Rees Bumper lower Chrome Moulding.	Calc'd.	250(SN) ✓
Rees Bumper Top Moulding.	Nu	150(SN) ✓
Rees Bumper Reflector Chrome Moulding x02	Nu	$50 \times 2 = 100(SN)$ ✓
Reverse Sensor	Del'd	280(SN) 100(SN)
Rees End Panel	Dented	585 ✓
Rees End Panel Top Garnish	Del'd	98.40 ✓
Rees End Panel Top Garnish clips.	Nu	10(SN) ✓
Rees End Panel Sealant.	Nu	60(SN) ✓
Rees End Panel Antenna Sensor	Nu	85.20 X
Rees End Panel Buzzer.	Del'd	60.10 ✓
Taillamp x02	LH at	$474.6 \times 2 = 949.20$ ✓ 474.60
Taillamp lower Apron x02	Repair	$195 \times 2 = 390$ X

4257.10

SLZ4428U.

Tailgate Dented	1100. ✓
Tailgate Lock Dmg	182.50. ✓
Tailgate Weatherstripe. ^{ut}	165.40. ✓
Tailgate Reflector x02 ^{LH} ^{ut}	413.20. ✓ 413.2xL=826.40
Tailgate Inner Trim Board ^{Cracked}	285.60 ✓
Tailgate Inner Trim Board Clips. ^{new}	30(SN) ✓
Tailgate Glass Moulding	120 ✓
Tailgate Glass Sealant.	60(SN) ✓
Wheel Wording.	^{new} 45.90 ✓
Hybrid Emblem	68 ✓
Spare Tyre Panel Top Cover ^{Dented}	306.60 ✓
Spare Tyre Panel Undercover ^{Dented}	225.10 ✓
Spare Tyre Panel Undercover Clips. ^{new}	30(SN) ✓
Tools Box Tray. ^{Cracked}	285.40 ✓
Rear Exhaust Pipe. ^{HL new}	598.60 X
Rear Fender Inner Trim Board x02	305.2xL=610.40
Rear Fender Inner Trim Board clips.	^{new} 60(SN) X

4999.90

SLZ4428U.

Panel Beating (Front)	1200 600
Spray Painting (Front)	800 600
Wiring (Front)	50 30
To remove condenser and to top up air con gas.	100 60
To remove radiator and to top up coolant.	100 60
To spray tuff coat (Front)	100 50
Panel Beating (Rear)	1200 800
Spray Painting (Rear)	1200 800
Wiring (Rear)	50 30
To remove reverse sensor	100 50
To remove rear camera.	100 50
To spray tuff coat.	150 80
To remove upholstery.	150 80
To transfer tailgate fittings.	150 80
To remove tailgate glass	180 120
To remove exhaust pipe.	150 X

5780

25,491.20

hist: 11143.30
Len 20% 8914.64
S.N: 1050

Labour: 3490
total: 13454.64
4/s: 10.7K.
11 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: