

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003814/QGS3Q2
Date: 05/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100392591
Claimant Vehicle No :	PA8954A	Insured Vehicle No :	SJK7952E
Date of Loss:	11/01/2021	Nature of Claim:	TP
		Claim No:	6599544875SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA8954A	Engine No:	ISBE428522038743
Make & Model:	KING LONG XMQ6117K, 6.7 (A)	Chassis No:	LA6R1FSH0DB101095
Reg. Date:	08/11/2013 (Man. Year: 2013)	Odometer:	425105 km
Colour:	Multi-colour		
Engine Capacity:	6693 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Firemax 6 mm	Rear Left Side:	Firemax 6 mm
Front Right Side:	Firemax 6 mm	Rear Right Side:	Firemax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,101.00	1,332.50	1,768.50	57.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	2,030.00	1,300.00	39.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,431.00	3,362.50	3,068.50	47.71
+ GST 7.00/7.00% (S\$)	450.17	235.38	214.79	47.71

Nett Amount (S\$)	6,881.17	3,597.88	3,283.29	47.71
+ Loss of Use (5.0 x S\$150.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,349.88		

INSPECTION

Date of Assignment: 24/03/2021

Date Inspected: 25/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Connect3 (HQ)
566 Woodlands Road
Singapore 728697

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	3		*RH COMPARTMENT OUTER HANDLE	Scratched	555.00 F	*480.00 FL
2	1		*RH COMPARTMENT COVER	Repair	1,350.00 F	*- FL
3	2		*RH REFLECTOR LAMP ASSY	Cracked	276.00 FS	*276.00 FS
4	1		*RH SIDE LAMP	Crumpled	255.00 F	*255.00 FL
5	1		*REAR RH RIM COVER	Cut	650.00 FS	*380.00 FS
6	1		*EXCURSION BUS STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,101.00	1,406.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	73.50
Total Parts (\$)	3,101.00	1,332.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES	New	1,500.00	600.00
2	SPRAY PAINTING WITH LINING	New	1,800.00	1,400.00
3	CHECK WIRING	New	30.00	30.00
Gross Labour Cost (\$\$)			3,330.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >