

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21003816/GPA3Q2

Date:

17/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SBZ2969G

Date of Loss: 23/03/2021

Policy No:

2070153250

Insured Vehicle No :

GBK7352G

Nature of Claim:

TP

Claim No:

4690214456SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SBZ2969G**

Make & Model: SKODA KODIAQ, 2.0 TSI 4X4 (A)

Reg. Date: 16/05/2019 (Man. Year: 2019)

Colour: Black

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CZP208965

Chassis No: TMBMD9NS6K8061068

Odometer: 35671 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R19

Front Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Tyre Size:

235/50 R19

Rear Left Side:

Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,590.91	5,059.77	531.14	9.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	790.00	530.00	260.00	32.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,380.91	5,589.77	791.14	12.40
+ GST 7.00/7.00% (S\$)	446.66	391.28	55.38	12.40

Nett Amount (S\$)	6,827.57	5,981.05	846.52	12.40
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		6,681.05		

INSPECTION

Date of Assignment: 24/03/2021

Date Inspected: 31/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Buckled	2,875.00 FL	*2,875.00 FL
2	1		*FRONT DOOR PROTECTOR LH	Necessary	372.00 FL	*372.00 FL
3	1		*FRONT DOOR RUBBER (AT DOOR) LH	Necessary	186.00 FL	*186.00 FL
4	1		*FRONT DOOR RUBBER (AT DOOR) TOP LH	Not Necessary	462.00 FL	*- FL
5	1		*SIDE MIRROR COVER LOWER W MOTOR ARM LH	Cut	891.25 FL	*891.25 FL
6	1		*SIDE MIRROR SIGNAL LAMP LH	Not Necessary	128.15 FL	*- FL
7	1		*SIDE MIRROR COVER	Cut	197.95 FS	*197.95 FS
8	1		*SOUND PROOFING CERAMIC/GLASS COATING AND SIDE MIRROR WRAP	Necessary	970.00 FS	*970.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,082.35	5,492.20
- List Item Discount on L Items 10.00/10.00% (\$)	491.44	432.43
Total Parts (\$)	5,590.91	5,059.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR /FACILITATE REPAIR	New	120.00	60.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	30.00	0.00
4	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD TO KNOCK & REPAIR FRONT INNER PANELS INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	300.00	200.00
5	TO SPRAY FRONT DOOR LH ,SIDE MIRROR COVER LH	New	300.00	250.00
Gross Labour Cost (\$\$)			790.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >