



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 3216S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SET FORK FORK (CONSISTENT)	TO REPAIR SEE LABOUR	550.00	-
1	FRONT FORK BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	180.00	-
1	FRONT FENDER (BLUE) (CONSISTENT)	CUT	250.00	122.00
1	FRONT FENDER (BLACK) (CONSISTENT)	NOT NECESSARY	180.00	-
1	BRAKE DISC (CONSISTENT)	NOT NECESSARY	350.00	-
1	FRONT FAIRING INNER (CONSISTENT)	CUT	350.00	165.00
1	FRONT FAIRING OUTER (CONSISTENT)	CUT	350.00	165.00
2	SIGNAL LAMP (CONSISTENT)	O/S NOT NECESSARY / N/S CUT	280.00	100.00
1	FRONT HEADLAMP FAIRNG (BLUE) (CONSISTENT)	CUT	250.00	105.00
1	FRONT HEADLAMP FAIRNG (BLACK) (CONSISTENT)	NOT NECESSARY	250.00	-
1	FRONT HEADLAMP (CONSISTENT)	CUT	450.00	195.00
1	SET WING MIRROR (CONSISTENT)	BROKEN	120.00	120.00
1	HANDLE BAR (CONSISTENT)	BENT	350.00	200.00
1	SET BALANCER (CONSISTENT)	CUT	100.00	80.00
1	REAR LH FAIRING (CONSISTENT)	CUT	600.00	250.00
1	FOOTREST (CONSISTENT)	TORN	120.00	120.00
1	FOOTREST BRACKET (CONSISTENT)	BENT	90.00	90.00
1	FOOTREST RUBBER (CONSISTENT)	TORN	90.00	60.00
1	PILLION FOOTREST (CONSISTENT)	MISSING	120.00	100.00
1	PILLION FOOTREST BRACKET (CONSISTENT)	BROKEN	90.00	50.00
1	STAND (CONSISTENT)	BENT	80.00	60.00
1	REAR FENDER (CONSISTENT)	NOT NECESSARY	250.00	-
1	TAILLAMP (CONSISTENT)	NOT NECESSARY	250.00	-
	LESS 10% DISCOUNT		-570.00	-198.20
			5,130.00	1,783.80
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	IU UNIT (SN) (CONSISTENT)	CUT	156.00	156.00

Report Ref No. CC4/ASM21003818/T1ps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HELMET (SN) (CONSISTENT)	CRACKED	300.00	150.00
1	BOX (SN) (CONSISTENT)	CUT	500.00	200.00
1	RIM (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
1	TYRE (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
2	GEAR SHAFT OIL SEAL (SN) (CONSISTENT)	NOT NECESSARY	24.00	-
1	BOT FORK OIL SEAL (SN) (CONSISTENT)	NECESSARY	120.00	80.00
1	FORK OIL (SN) (CONSISTENT)	NECESSARY	60.00	60.00
			1,810.00	646.00
	LABOUR			
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TO CHECK FORK ALIGNMENT.		200.00	120.00
	TO R&R EXHAUST SILENCER .	NOT NECESSARY	200.00	-
	TO REALIGN BODY FRAME .	NOT NECESSARY	350.00	-
	TO R&R SUSPENSION ,HANDLE BAR ,HEADLAMP & FAIRING.INCLUSIVE OF THE REPAIR OF SET FORK FORK AND FRONT FORK BRACKET.		400.00	200.00
	TO SPRAY FENDER ,SIDE FAIRINGS AND AFFECTED AREAS .		500.00	250.00
			1,710.00	600.00
GRAND TOTAL			8,650.00	3,029.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CC4/ASM21003818/T1ps3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.