

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21003826/QTF3E2

Date: 06/05/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00109262000
Claimant Vehicle No : SGA12C **Insured Vehicle No :** XE5948Y
Date of Loss: 20/03/2021 Nature of Claim: TP Claim No: SNM21D201619/C02/XE5948Y/THAMY

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGA12C**
Make & Model: VOLKSWAGEN GOLF GTI, 2.0 TSI (A) Engine No: CHH010045
Reg. Date: 27/09/2013 (Man. Year: 2013) Chassis No: WVVZZZAUZEW055330
Colour: Silver Odometer: 76139 km
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 235/35 R19 Rear Tyre Size: 235/35 R19
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,702.00	4,187.00	1,515.00	26.57
Miscellaneous Items	350.00	370.00	-20.00	-5.71
Labour	1,113.00	1,079.40	33.60	3.02
Paintwork Labour	650.16	650.16	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,815.16	6,286.56	1,528.60	19.56
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	7,815.16	5,050.00	2,765.16	35.38
+ GST 7.00/7.00% (S\$)	547.06	353.50	193.56	35.38
Nett Amount (S\$)	8,362.22	5,403.50	2,958.72	35.38

INSPECTION

Date of Assignment: 25/03/2021 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected: 25/03/2021 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)
6 Marsiling Lane
Singapore 739145
Estimated Period of Repair: 7.0 days

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	350.00	370.00
			Sub Total (\$\$)	370.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR OF SPRAY PAINTING	New	650.16	650.16
<u>Labour Items</u>				
2	LABOUR OF PANEL BEATING	New	1,113.00	1,079.40
			Gross Labour Cost (\$\$)	1,729.56

Report was unsubmitted during this print-out.

< END OF ESTIMATES >