

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO21003829/QKqf3e2 Ref: 50 RAFFLES PLACE #03-03 Date: 23/04/2021 SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SMF 503E** SLC 8686K Veh. Inspected Policy No. D20MTPV014169 Coverage (\$) 0.00 Claim No. CMTD2003420/RUC Excess (\$) 0.00 **GRACE TEO Assign Date** 25/03/2021 Assign From **Vehicle Particulars & Condition** 2. B.M.W. 523I A 2497 Make & Model C.C HIDDEN 2010 Engine No. Year of Reg. WBAFP32040C543965 **GREY** Chassis No. Colour 165793 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 245/40Z R19 ARIVO 6 mm 245/40Z R19 ARIVO L/H Front Tyre 6 mm 245/40Z R19 ARIVO R/H Rear Tyre 6 mm **ARIVO** L/H Rear Tyre 245/40Z R19 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. 5. **General Information** 07/11/2020 06/04/2021 (12:00 PM) **Accident Date** Inspect Date / Time 160 SIN MING DRIVE #02-09 SIN MING AUTOCITY Survey held at Repairer 833 MOTORSPORTS 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/SMO21003829/QKqf3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Estimate Days of Repair

Inspected By

5b.

KONG SENG CHEONG

Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

3 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser