

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21003835/T1vf3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA Date: 07/04/2021 **TOWERSINGAPORE 068811** ATTN: YU DOMINIC YISHAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 9333E GBC 8770T** Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S1M0368W Excess (\$) 0.00 YU DOMINIC YISHAN **Assign Date** 25/03/2021 Assign From **Vehicle Particulars & Condition** 2. 2497 Make & Model **KIA K2500** c.c HIDDEN 2014 Engine No. Year of Reg. KNCSJX76LE7827184 WHITE Chassis No. Colour 473327 KM Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15 YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 195 R15 6 mm 155 R12 (D) YOKOHAMA R/H Rear Tyre 6/6 mm YOKOHAMA L/H Rear Tyre 155 R12 (D) 6/6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 23/03/2021 25/03/2021 (03:00 PM) Inspect Date / Time Accident Date SAFE AUTO Survey held at 1 KAKI BUKIT AVE 6 #01-52 AUTOBAY KAKI BUKIT SINGAPORE 417883 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Report Ref No. CS3/ASM21003835/T1vf3e2

Estimate Days of Repair

Inspected By

5b.

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

7 Working Days

Automotive Assessor

ESTIMATED NORMAL PERIOD FOR REPAIR: