

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INSI	PECTION REPOR	T	
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21003841/Qvf3e2	
	8 SHENTON WAY TOWERSINGAPOR		Date	: 12/04/2021	
	ATTN: YU DOMINI	C YISHAN	Code	e: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 9799U	Veh. Inspected	FBR 18G	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S1M035YE	Excess (\$)	0.00	
	Assign From	YU DOMINIC YISHAN	Assign Date	25/03/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA CZD300A	c.c	292	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	MH3SH0848LK013761	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	140/70-14	DUNLOP	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	140/70-17	DUNLOP	5 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S	AND N/S BODY.		
5.	General Information				
	Accident Date	19/03/2021	Inspect Date / Time	25/03/2021 (02:00 PM)	
	Survey held at	ENG SOON PAINTING SVC			
	BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800-\$3,300				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/ASM21003841/Qvf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser