

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21003842/KPS3Q2

Date:

18/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900259470

Claimant Vehicle No : SLH6000B**Insured Vehicle No :**

SMR2139Y

Date of Loss: 23/03/2021

Nature of Claim:

TP

Claim No:

4165844501SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLH6000B**

Make & Model: BMW X3 SDRIVE, 2.0 20i LED SR NAV (A)

Engine No:

A1961540N20B20A

Reg. Date: 26/01/2017 (Man. Year: 2016)

Chassis No:

WBAWY920700R99847

Colour: Metallic Grey

Odometer:

78348 km

Engine Capacity: 1997 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18

Rear Tyre Size:

245/50 R18

Front Left Side: Dunlop 8 mm

Rear Left Side:

Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side:

Dunlop 8 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,681.14	3,509.66	171.48	4.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	790.00	380.00	32.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,851.14	4,299.66	551.48	11.37
+ GST 7.00/7.00% (S\$)	339.58	300.98	38.60	11.37

Nett Amount (S\$)	5,190.72	4,600.64	590.08	11.37
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,052.64		

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 29/03/2021

Estimated Period of Repair: 3.0 days

Inspected At: Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA (M SPORT)	Buckled	2,300.00 FL	*2,300.00 FL
2	1		*REAR N/S BUMPER REFLECTOR	Missing	77.80 FL	*77.80 FL
3	1		*REAR BUMPER LOWER SPOILER	Buckled / Mtg Distorted	392.50 FL	*392.50 FL
4	1		*REAR N/S EXHAUST CHROME PIPE	Dented	191.85 FL	*191.85 FL
5	1		*REAR N/S PARKING SENSOR	Dented	257.90 FL	*257.90 FL
6	1		*REAR N/S PARKING SENSOR O RING	Necessary	12.50 FL	*12.50 FL
7	1		*REAR N/S BUMPER BRACKET	Cracked	194.20 FL	*194.20 FL
8	1		*REAR N/S FENDER AIR VENT	Serviceable	180.50 FL	*- FL
9	1		*REAR BUMPER CLIP & REIVET	Necessary	50.00 FS	*50.00 FS
10	1		*REAR N/S BUMPER INNER PARTS	Cracked	215.00 FL	*215.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,872.25	3,691.75
- List Item Discount on L Items 5.00/5.00% (\$)	191.11	182.09
Total Parts (\$)	3,681.14	3,509.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRING REAR PARKING SENSOR WIRE	New	40.00	40.00
2	TO REMOVE REAR EXHAUST FOR RENEW CHROME PIPE	New	30.00	30.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	600.00	420.00
4	TO REMOVE CUT-OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	500.00	300.00
Gross Labour Cost (\$\$)			1,170.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >