LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21003858/GTF3E2

Date: 08/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210003789

Claimant Vehicle ODI/7000 Insurance Pte. Ltd. Policy No: 7210003789

No: GBK7992J Insured Vehicle No: SJU1512D

Date of Loss: 24/03/2021 Nature of Claim: TP Claim No: 4512032818SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBK7992J

 Make & Model:
 NISSAN NV200, 1.6 DX (A)
 Engine No:
 HR16177955D

 Reg. Date:
 02/12/2020 (Man. Year: 2020)
 Chassis No:
 VM20161878

 Colour:
 Silver
 Odometer:
 6029 km

Engine Capacity: 1597 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165/80 R14 Rear Tyre Size: 165/80 R14
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm
Front Right Side: Bridgestone 8 mm
Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 25/03/2021 Inspected At: 8 Kaki Bukit Ave4 #03-27 Repairer : Garage 13 Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	0.00 F	*- F
2	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1	*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*-F
4	1	*REAR END PANEL	Repair	0.00 F	*- F
5	1	*REAR LH TAILLAMP	Scratched	0.00 F	*- F
6	1	*TAILGATE	Repair	0.00 F	*- F
7	4	*TAILGATE EMBLEM	Necessary	0.00 F	*- F
8	1	*REAR BODY PANEL	Repair	0.00 F	*- F
F=Fra	anchise part.				
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted d	luring this print-out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >