

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21003860/UPA3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070006719
Claimant Vehicle No :	SFJ4005L	Insured Vehicle No :	SMR7264K
Date of Loss:	25/03/2021	Nature of Claim:	TP
		Claim No:	3373026809SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFJ4005L	Engine No:	CVK077128
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF46KA041867
Reg. Date:	29/03/2019 (Man. Year: 2019)	Odometer:	57721 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,744.02	8,759.56	1,984.46	18.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	850.00	1,190.00	58.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,784.02	9,609.56	3,174.46	24.83
Approved Total (Overridden) (S\$)		7,600.00		

Nett Amount (S\$)	12,784.02	7,600.00	5,184.02	40.55
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,902.00		
Global Sum Settlement (S\$)		7,900.00		

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 25/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Hup Motor Trading & Service (HQ)
 Blk 9004 Tampines Street 93, #01-120
 Singapore 528838

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Warped	1,610.95 FL	*1,610.95 FL
2	1		*FRONT BUMPER O/S SIDE RETAINER	Not Necessary	25.55 FL	*- FL
3	1		*SET FRONT BUMPER CLIPS & REVETS	Necessary	169.55 FL	*60.00 FL
4	1		*FRONT BUMPER O/S SENSOR	Serviceable	208.85 FL	*- FL
5	1		*O/S HEAD LAMP ASSY	Scratched	7,486.65 FL	*7,486.65 FL
6	1		*FRONT O/S FENDER	Dented / Bent	575.25 FL	*575.25 FL
7	1		*FRONT O/S FENDER GLASS SHIELD	Not Necessary	177.25 FL	*- FL
8	1		*SET FRONT O/S FENDER GLASS SHIELD CLIPS & REVETS	Not Necessary	53.85 FL	*- FL
9	1		*FRONT O/S SPORT RIM	Not Necessary	1,629.90 FL	*- FL
					Sub Total (S\$)	11,937.80
					- List Item Discount on L Items 10.00/10.00% (S\$)	1,193.78
					Total Parts (S\$)	10,744.02

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	50.00	20.00
2	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	120.00	0.00
3	TO DIAGNOSE & RE-SET HEAD LIGHT FAULT CODE FOR REFIX	New	120.00	50.00
4	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	750.00	300.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	950.00	450.00
6	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	50.00	30.00
Gross Labour Cost (S\$)			2,040.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >