

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21003861/EVF3N2**Date:** 14/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00023252100

**Claimant Vehicle  
No :** GBJ4508A**Insured Vehicle  
No :** GBL8383E

Date of Loss: 09/03/2021

Nature of Claim: TP

Claim  
No: SNM21D201585C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBJ4508A**

Make &amp; Model: NISSAN NV350, 2.5 (A)

Engine No: YD25046870B

Reg. Date: 22/04/2019 (Man. Year: 2019)

Chassis No: JN1MC2E26Z0031031

Colour: Grey

Odometer: 72744 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195R15C

Rear Tyre Size:

195R15C

Front Left Side: Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side:

Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,743.67	3,499.54	3,244.13	48.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,060.00	1,440.00	57.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,243.67</b>	<b>4,559.54</b>	<b>4,684.13</b>	<b>50.67</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,700.00</b>		
<b>(\$\$)</b>	9,243.67	3,700.00	5,543.67	59.97
<b>+ GST 7.00/7.00% (\$\$)</b>	647.06	259.00	388.06	59.97
<b>Nett Amount (\$\$)</b>	<b>9,890.73</b>	<b>3,959.00</b>	<b>5,931.73</b>	<b>59.97</b>

**INSPECTION**

Date of Assignment: 25/03/2021

Date Inspected: 26/01/2022 Inspected At:

Efficient Motor & Engineering Works Pte Ltd (HQ)  
56 Loyang Way #06-07, Loyang Enterprise  
Building  
Singapore 508775

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 Apr 2022)	
<b>Parts:</b>	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ4508A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	667.20 FL	*667.20 FL
2	6		*REAR BUMPER SIDE CLIP LH/RH	Not Necessary	72.60 FL	*- FL
3	1		*REAR BUMPER STEP PANEL	Dented	252.30 FL	*252.30 FL
4	1		*REAR END PANEL OUTER	Repair	360.90 FL	*- FL
5	1		*TAILGATE	Dented	2,280.00 FL	*1,998.30 FL
6	1		*TAILGATE LOCK LOWER	Not Necessary	528.60 FL	*- FL
7	1		*TAILGATE LOCK UPPER	Bent	178.80 FL	*178.80 FL
8	1		*TAILGATE LOCK COVER	Cut	84.00 FL	*84.00 FL
9	1		*TAILGATE LOCK ACTUATOR	Not Necessary	408.40 FL	*- FL
10	1		*TAILGATE WEATHERSTRIP	Torn	228.00 FL	*150.00 FL
11	1		*TAILGATE CHROME GARNISH	Not Necessary	535.70 FL	*- FL
12	2		*TAILGATE STAY LH/RH	Not Necessary	431.80 FL	*- FL
13	1		*TAILGATE LOGO	Necessary	115.20 FL	*100.00 FL
14	1		*TAILGATE EMBLEM NV350 URBAN	Necessary	156.00 FL	*80.00 FL
15	2		*TAIL LAMP LH/RH	Not Necessary	576.80 FL	*- FL
16	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
18	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
19	1		*REAR NO PLATE	Not Necessary	45.00 FS	*- FS
20	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
21	1		*PAN PACIFIC METAL PLATE	Necessary	80.00 FS	*50.00 FS
22	1		*REAR PANEL CHECKER PANEL	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,431.30</b>	<b>3,850.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	687.63	351.06
<b>Total Parts (\$\$)</b>	<b>6,743.67</b>	<b>3,499.54</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CUT/WELD PANELS,PANEL BEAT & ALIGN TAILGATE,REMOVE & REPLACE DAMAGED PARTS	New	1,000.00	400.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	50.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO REMOVE & REPLACE REVERSE SENSOR	New	100.00	30.00
5	TO SPRAY PAINTING FOR REAR PORTIONS & AFFECTED AREAS	New	1,000.00	400.00
6	TO REMOVE & TRANSFER TAILGATE COMPONENTS	New	150.00	50.00
7	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS	New	150.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,500.00</b>	<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >