

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003864/T1RS3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900108344
Claimant Vehicle No :	SHC6047R	Insured Vehicle No :	SMM3357D
Date of Loss:	25/03/2021	Nature of Claim:	TP
		Claim No:	9319902947SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6047R		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LELU040543
Reg. Date:	22/03/2021 (Man. Year: 2020)	Chassis No:	KMHC851CVLU240856
Colour:	Silver	Odometer:	835 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,372.96	397.12	2,975.84	88.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,110.00	1,270.00	53.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,752.96	1,507.12	4,245.84	73.80
+ GST 7.00/7.00% (S\$)	402.71	105.50	297.21	73.80

Nett Amount (S\$)	6,155.67	1,612.62	4,543.05	73.80
		+ Car Rental (5.0 x S\$62.97/day) (S\$)	314.85	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	1,929.47	

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 25/03/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WHEEL COVER	Cut	346.40 FL	*346.40 FL
2	1		*REAR BUMPER	Repair	459.40 FL	*- FL
3	1		*REAR BUMPER O/S SIDE BRACKET	Not Necessary	33.10 FL	*- FL
4	1		*REAR O/S RIM	Not Necessary	1,091.50 FL	*- FL
5	1		*REAR O/S LOWER ARM	Not Necessary	393.10 FL	*- FL
6	1		*REAR O/S ASSIST ARM	Not Necessary	92.80 FL	*- FL
7	1		*REAR O/S TRAILING ARM	Not Necessary	121.00 FL	*- FL
8	1		*REAR O/S SHOCK ABSORBER	Not Necessary	230.50 FL	*- FL
9	1		*REAR O/S KNUCKLE BEARING	Not Necessary	454.00 FL	*- FL
10	1		*REAR O/S KNUCKLE ARM	Not Necessary	386.90 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
12	1		*SET O/S DOOR STICKERS	Necessary	100.00 FS	*80.00 FS
13	1		*REAR O/S FENDER STICKER	Necessary	60.00 FS	*40.00 FS
14	1		*REAR O/S TYRE	Not Necessary	200.00 FS	*- FS
15	1		*SET REAR O/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
16	1		*SET SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,094.70	466.40
- List Item Discount on L Items 20.00/20.00% (\$)	721.74	69.28
Total Parts (\$)	3,372.96	397.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND REPLACE THE REAR O/S UNDERCARRIAGE	New	250.00	0.00
2	TO CHECK REAR O/S WHEEL ALIGNMENT	New	80.00	80.00
3	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
4	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
5	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE REAR O/S FENDER ETC	New	800.00	400.00
6	TO PUTTY AND SPRAY PAINTING ON REAR O/S DOOR ,O/S ROCKER PANEL GARNISH ,REAR O/S FENDER ,REAR BUMPER	New	800.00	600.00
7	TO APPLY RUSTPROOF ON REPAIR PANELS	New	150.00	0.00
Gross Labour Cost (\$\$)			2,380.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >