

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003867/KRA3Q2
Date: 17/06/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100499362
Claimant Vehicle No :	SMR4451G	Insured Vehicle No :	SGA8866C
Date of Loss:	23/03/2021	Nature of Claim:	TP
		Claim No:	6204666679SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR4451G	Engine No:	LEB1443748
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP51336319
Reg. Date:	06/01/2020 (Man. Year: 2018)	Odometer:	14393 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,053.36	1,893.20	4,160.16	68.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	1,980.00	2,240.00	53.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,273.36	3,873.20	6,400.16	62.30
Approved Total (Overridden) (S\$)		3,100.00		

Nett Amount (S\$)	10,273.36	3,100.00	7,173.36	69.82
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,527.45		

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 25/03/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Caris Autoworks Pte Ltd (HQ)
#05-03 160SIN MING DRIVE
Singapore 575722**Adjuster:** KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR ASSY (FRONT RIGHT)	Bent	792.40 FL	*792.40 FL
2	1		*DOOR ASSY (REAR RIGHT)	Bent	736.20 FL	*736.20 FL
3	1		*DOOR PANEL (FRONT RIGHT)	Repeated	742.80 FL	*- FL
4	1		*DOOR RUBBER CHANNEL (FRONT & REAR RIGHT) (1SET)	Serviceable	391.60 FL	*- FL
5	1		*MANGUARD (FRONT RIGHT)	Bent	425.40 FL	*425.40 FL
6	1		*DOOR SIDE SPOILER (FRONT RIGHT)	Repair	432.40 FL	*- FL
7	1		*POWER WINDOW & REGULATOR (FRONT RIGHT)	Serviceable	400.70 FL	*- FL
8	1		*RIM (FRONT & REAR RIGHT)	Dented	1,371.84 FS	*280.00 FS
9	2		*S/ABSORBER (FRONT & REAR RIGHT)	Serviceable	616.20 FL	*- FL
10	2		*WHEEL BEATING (FRONT & REAR RIGHT)	Serviceable	272.60 FL	*- FL
11	2		*LOWER ARM (FRONT & REAR RIGHT)	Serviceable	341.60 FL	*- FL
12	2		*LOWER LINKAGE ROD (FRONT & REAR RIGHT)	Serviceable	97.00 FL	*- FL
13	2		*WHEEL KNUCKLE (FRONT & REAR RIGHT)	Serviceable	503.00 FL	*- FL
14	1		*BODY CLIPS	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,203.74	2,284.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,150.38	390.80
Total Parts (\$\$)	6,053.36	1,893.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL KNOCKING	New	1,800.00	700.00
2	SPRAY PAINTING	New	1,600.00	1,200.00
3	WHEEL ALIGNMENT (COMPUTRISED)	New	120.00	60.00
4	WIRE CHECKING & DIAGNOSTIC	New	150.00	20.00
5	LABOUR FOR REPLACING S/ABSORBER & OTHER PARTS	New	550.00	0.00
			Gross Labour Cost (S\$)	4,220.00
				1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >